

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23003934/RNY3Q2**Date:** 27/07/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00136982201
Claimant Vehicle No :	SNH9721K	Insured Vehicle No :	YN8984M
Date of Loss:	12/04/2023	Nature of Claim:	TP
		Claim No:	SNM23D202685/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNH9721K	Engine No:	27091031566396
Make & Model:	INFINITI Q30, 2.0 (A)	Chassis No:	SJKDDAH15U2000630
Reg. Date:	28/11/2018 (Man. Year: 2018)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,458.42	27,706.76	7,751.66	21.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,501.00	6,378.00	2,123.00	24.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	43,959.42	34,084.76	9,874.66	22.46
+ GST 8.00/8.00% (S\$)	3,516.75	2,726.78	789.97	22.46
Nett Amount (S\$)	47,476.17	36,811.54	10,664.63	22.46

INSPECTION

Date of Assignment:	14/04/2023		
Date Inspected:	10/05/2023	Inspected At:	Wearnes automotive Pte Ltd (HQ) 45 LENG KEE ROAD Singapore 159103
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD RASUL**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Jul 2023)
Parts: 144	INFINITI Q30 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SNH9721K)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NUMBER PLATE & HOLDER	Scratched	120.00 FS	*60.00 FS
2	1		*BUMPER SET -RR Q30	Deformed	3,056.80 FS	*2,421.44 FS
3	1		*BUMPER RR LOWER MOUL	Deformed	1,261.00 FS	*962.55 FS
4	1		*REINFORCEMENT -BUMPER	Bent	2,167.70 FS	*1,950.93 FS
5	1		*RETAINER -BUMPER Q30	Cracked	580.40 FS	*522.36 FS
6	1		*FINISHER -REAR B LH	Not Necessary	223.70 FS	*- FS
7	1		*FINISHER -REAR B RH	Not Necessary	252.50 FS	*- FS
8	1		*DIFFUSER ASSY LH	Necessary	410.10 FS	*369.09 FS
9	1		*DIFFUSER ASSY RH	Necessary	410.10 FS	*369.09 FS
10	1		*RETAINER LH-RR BUMPE	Not Necessary	126.40 FS	*- FS
11	1		*RETAINER RH-RR BUMPE	Not Necessary	126.40 FS	*- FS
12	1		*TAILGATE Q30	Bent	8,740.00 FS	*7,240.32 FS
13	1		*FINISHER TAILGATE OU	Scratched	1,160.30 FS	*989.12 FS
14	1		*FINISHER ASSY CHROME	Necessary	4,819.30 FS	*3,143.03 FS
15	1		*WINDSCREEN RR TAILGATE	Necessary	5,990.20 FS	*4,617.41 FS
16	1		*EMBLEM -BACK DOOR	Necessary	119.90 FS	*107.91 FS
17	1		*ORNAMENT -BACK DOOR	Not Necessary	147.50 FS	*- FS
18	1		*HARNES -SUB,REA	Not Necessary	298.80 FS	*- FS
19	1		*REFLECTER LAMP REAR (LH)	Scratched	120.50 FS	*108.45 FS
20	1		*REFLECTER LAMP REAR (RH)	Scratched	120.50 FS	*108.45 FS
21	1		*TAILAMP REAR LH Q30	Scratched	1,814.10 FS	*1,391.40 FS
22	2		*COVER SONAR SENSOR F	Necessary	211.60 FS	*190.44 FS
23	2		*COVER SONAR RR OUTER	Necessary	211.60 FS	*190.44 FS
24	1		*D PRIMER GLASS & P	Necessary	46.90 FS	*42.21 FS
25	2		*SEALANT WINDSCREEN	Necessary	437.58 FS	*437.58 FS
26	1		*LAMP A-BACK UP LH	Scratched	821.16 FS	*821.16 FS
27	1		*LAMP A-BACK UP RH	Scratched	821.16 FS	*821.16 FS
28	2		*SENSOR ASSY	Not Working	842.22 FS	*842.22 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	35,458.42	27,706.76
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER ,LOWER BUMPER ,REAR TAILGATE , BUMPER BEAM ,TAILLAMP	New	3,200.00	2,000.00
2	TO SPRAYPAINT ON REAR BUMPER ,LOWER BUMPER ,REAR TAILGATE	New	3,200.00	2,400.00
3	TO REMOVE ,REFIT & TRANSFER REAR TAILGATE COMPONENTS	New	400.00	400.00
4	TO REPLACE REAR WINDSCREEN	New	800.00	800.00
5	TO INSTALL REAR WINDSCREEN FIL	New	280.00	280.00
6	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	621.00	498.00
			Gross Labour Cost (\$\$)	8,501.00
				6,378.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >