

Wah Hong Motors & Credit Pte Ltd (Co.Reg.No:199806235M)

38 Toh Guan Road East, #01-57, Enterprise Hub

Singapore 608581

Tel: +65 6773 7377 Email: motor@wahhong.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	WH1904
Policy No:	SP2005018895-01	Date of Loss:	13/04/2023
Vehicle Reg. No.:	SMS9704P	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ANG WEI LING		
Make/Model:	HYUNDAI I30 PDE, 1.4 T-GDI DCT (A)	Vehicle Reg. Date:	24/03/2020
Vehicle Colour:	RED		
Engine No:	G4LDKD112775	Chassis No:	TMAH3513VLJ118030
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	WAH HONG MOTORS & CREDIT PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	12,050.50
Miscellaneous Items	130.00
Labour	1,960.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	14,140.50
+ GST 8.00% (S\$)	1,131.24
Nett Amount (S\$)	15,271.74

This claim is handled by: TAN TING YI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 08 May 2023)**Parts:** 144 HYUNDAI I30 PDE 1.4 T-GDI DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Wah Hong Motors & Credit Pte Ltd **SMS9704P/08/05/2023 12:13****Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Headlamp RH/LH@2*\$2000 LH-CRA, RH-XNN	0.00	0.00	*4,000.00 FV
2	1		*Headlamp lower bracket RH/LH@.*\$55	0.00	0.00	*110.00 F ?XNN
3	1		*Front bumper	0.00	0.00	*600.00 F DD/CRA
4	1		*Front bumper side retainer RH/LH@2*\$80 LH	0.00	0.00	*160.00 F BT
5	1		*Center grille assy with logo badge	0.00	0.00	*1,300.00 F CRA
6	1		*Front reverse sensor RH/LH@2*\$190	0.00	0.00	*380.00 F Pshot
7	1		*Front carplate base	0.00	0.00	*35.00 F XNN
8	1		*Front towing cover	0.00	0.00	*15.00 F XNN
9	1		*Front bumper lower grille	0.00	0.00	*75.00 F CRA
10	1		*Front bumper lower cover	0.00	0.00	*250.00 F XNN
11	1		*Front bumper sponge	0.00	0.00	*120.00 F CRA
12	1		*Front reinforcement	0.00	0.00	*350.00 F XNN
13	1		*Support panel	0.00	0.00	*1,300.00 F XNN
14	1		*Condenser	0.00	0.00	*1,400.00 F XNN
15	1		*Radiator	0.00	0.00	*500.00 F XNN
16	1		*Radiator air guide RH/LH@2*\$90	0.00	0.00	*180.00 F XNN
17	1		*Radiator top garnish	0.00	0.00	*180.00 F XNN
18	1		*Boot lid (repair refer to labour) R	0.00	0.00	*-F
19	1		*Front fender RH (repair refer to labour) R	0.00	0.00	*-F
20	1		*Front fender LH (repair refer to labour) R	0.00	0.00	*-F

F=Franchise part.

Sub Total (\$\$)	10,955.00
+ Margin on L,N Items 10.00% (\$\$)	1,095.50
Total Parts (\$\$)	12,050.50

Wah Hong Motors & Credit Pte Ltd/SMS9704P/08/05/2023 12:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	Center grille clip	35.00 ^{25 NE}
2	1	Front bumper clip	35.00 ^{NE}
3	1	Front carplate with holder	35.00 ^{BT}
4	1	Radiator top garnish clip	25.00 ^{20 NE}
Sub Total (S\$)			130.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	New	1,000.00 ⁶⁰⁰
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New	800.00 ⁵⁰⁰
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	New	60.00 ³⁰
4	Remove and refit aircon condenser, radiator, related pipes and hoses, vacuum and refill aircon gas	New	100.00 ^{2X}
Gross Labour Cost (S\$)			1,960.00

Wah Hong Motors & Credit Pte Ltd/SMS9704P/08/05/2023 12:13. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- Not authorise.
 - Excess = NIL
 - Resurvey before paint for P/P repair.
 - Survey by Simon Ho (6256 3561).

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Jun 2023)

Parts: 144 HYUNDAI I30 PDE 1.4 T-GDI DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Wah Hong Motors & Credit Pte Ltd/SMS9704P/14/06/2023 20:15

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Center grille sensor bracket	0.00	0.00	*65.00 F
2	1		*Center grille top bracket LH	0.00	0.00	*55.00 F
F=Franchise part.						
Sub Total (\$\$)						120.00
+ Margin on L,N Items 10.00% (\$\$)						12.00
Total Parts (\$\$)						132.00

Wah Hong Motors & Credit Pte Ltd/SMS9704P/14/06/2023 20:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS