



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23003939/Rny3e2 Date: 09/06/2023  Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SBS 6455H	Veh. Inspected	SBS 8862C
Policy No.	D-22099843MFBP	Coverage (\$)	0.00
Claim No.	D23001228MFBP	Excess (\$)	0.00
Assign From	AINI BINTE	Assign Date	14/04/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	SCANIA KUB4X2 9.3L A	c.c	9290
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	YS2K4X20001865959	Colour	MULTI COLOUR
Odometer	1003027 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	PIRELLI	8 mm
L/H Front Tyre	275/70 R22.5	PIRELLI	8 mm
R/H Rear Tyre	275/70 R22.5 (D)	PIRELLI	8/8 mm
L/H Rear Tyre	275/70 R22.5 (D)	PIRELLI	8/8 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	07/04/2023	Inspection Date	18/04/2023
Survey held at	SBS TRANSIT LTD (Branch) BUKIT BATOK ST 23 SINGAPORE 659519		
<b>5a. Remarks</b>			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	