



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBN 9708K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT FENDER	TO REPAIR SEE LABOUR	520.00	-
1	FRONT FAIRING	CUT	980.00	800.00
1	FRONT FAIRING (MATT)	CUT	850.00	480.00
1	FRONT INNER COVER (MATT)	CUT	680.00	300.00
1	METER COVER (MATT)	CUT	380.00	182.00
1	SIDE MIRROR (O/S)	CUT	480.00	110.00
1	HANDLE BAR	BENT	450.00	180.00
1	HANDLE BAR ENDS	SCRATCHED	150.00	38.00
2	HAND GRIPS	NOT NECESSARY	100.00	-
1	BRAKE LEVERS	SCRATCHED	380.00	110.00
2	FOOTSTEP PANEL	O/S CUT	690.00	280.00
2	FOOTSTEP LOWER PANEL	O/S CUT	570.00	245.00
1	EXHAUST ASSY	TWISTED / DENTED	2,750.00	1,150.00
1	EXHAUST PROTECTOR	DISTORTED	280.00	166.00
1	EXHAUST END CAP	DISTORTED	240.00	85.00
1	REAR COVER	TO REPAIR SEE LABOUR	680.00	-
	LESS 10% DISCOUNT		-1,018.00	-412.60
			9,162.00	3,713.40
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET NUMBER PLATE (SN)	NOT NECESSARY	38.00	-
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN)	NOT NECESSARY	90.00	-
1	REAR BOX (SN)	SERVICEABLE	580.00	-
1	REAR BOX BRACKET (SN)	NOT NECESSARY	180.00	-
1	STICKER (SN)	NOT NECESSARY	120.00	-
			1,094.00	-
<b><u>LABOUR</u></b>				
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING .	NOT NECESSARY	80.00	-

Report Ref No. CS/AGI23003944/Uvy3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PROVIDE LABOUR .INCLUSIVE OF THE REPAIR OF FRONT FENDER AND REAR COVER .	NOT NECESSARY	420.00	300.00
	TO REPAIR BODY FRAME .		480.00	-
	TO RESPRAY PAINTING.		600.00	200.00
			1,580.00	500.00
<b>GRAND TOTAL</b>			<b>11,836.00</b>	<b>4,213.40</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,300.00</b>

Report Ref No. CS/AGI23003944/Uvy3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.