

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT | | | | | |
|------------------------------|---|--|--------------------|-----------------------|------------------------|
| | SOMPO INSURAN | Re | | S3/SMO23003947/Aqy3m4 | |
| | 50 RAFFLES PLAC | Da | | 9/05/2023 | |
| | SINGAPORE LAND | Ба | ic. • | 0/00/2020 | |
| | | | Co | de: S | MO |
| 1. | Policy Particulars :- (THIRD PARTY CLAIM) | | | | |
| | Insured Veh. | SKX 8293L | Veh. Inspected | S | NJ 2645H |
| | Policy No. | | Coverage (\$) | 0 | .00 |
| | Claim No. | CMTD2301508/SYH | Excess (\$) | 0 | .00 |
| | Assign From | IRENE HENRY | Assign Date | 1 | 7/04/2023 |
| 2. | . Vehicle Particulars & Condition | | | | |
| | Make & Model | RENAULT KADJAR | c.c | 1 | 461 |
| | Engine No. | HIDDEN | Year of Reg. | 2 | 017 |
| | Chassis No. | VF1RFE00X57210069 | Colour | G | GREY |
| | Odometer | 108151 KM | Steering | 11 | N ORDER |
| | Brakes | IN ORDER | Modification | S | PORTS RIM |
| | General | GOOD | | | |
| 3. | Conditions of Tyres | | | | |
| | | Size | Make | В | Balance |
| | R/H Front Tyre | 225/45 R19 | GOODYEAR | 6 | mm |
| | L/H Front Tyre | 225/45 R19 | GOODYEAR | 6 | mm |
| | R/H Rear Tyre | 225/45 R19 | GOODYEAR | 6 | mm |
| | L/H Rear Tyre | 225/45 R19 | GOODYEAR | 6 | mm |
| 4. Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORT | | | | |
| 5. | 5. General Information | | | | |
| | Accident Date | 13/04/2023 | Inspect Date / Tim | e 1 | 7/04/2023 (03:11 PM) |
| | Survey held at | A-TEC AUTOMOTIVE PTE LTD | | | |
| | | 8 KAKI BUKIT AVE 4 #05-27 PREMIER SINGAPORE 415875 | | | |
| 5a. Remarks | | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,500-\$6,500 | | | | |
| 5b. | 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days | | | | |

Report Ref No. CS3/SMO23003947/Aqy3m4

Inspected By

ADRIAN LING WAI PING

Licensed Appraiser

K.K.LAU CPT(RET)

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

 ${\tt BEng(Hons),B.Bus,MBA,PEng,PE,\,MInstAEA,MASME,MIRTE}$

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.