

ENG SOON PAINTING SERVICES

Blk 4 Yew Tee Ind Est 393-J
Woodlands Road
Singapore 677978
Tel: 67606271 Fax: 67646676

fl
04 days
Akid 8700 5631
18/04/23 1100hrs

Date: 17/04/2023

Attn: Motor Claim Dept

Repair cost of TOYOTA HIACE COMMUTER GL - PC3215Y ✓

SN	DESCRIPTION	AMOUNT	
1	Rear bumper	\$ 688.40	DT 522.4
2	Rear bumper retainer LH & RH	\$ 116.40	?
3	Rear bumper lower bracket (4x)	\$ 118.40	?
4	Rear end panel outer	\$ 580.40	?
5	Rear end panel top plate	\$ 198.00	?
6	Tailgate	\$ 2,250.00	DT 1855
7	Tailgate 'LOGO' emblem	\$ 72.70	NEC ✓
8	Tailgate 'HIACE' emblem	\$ 51.70	NEC ✓
9	Tailgate 'GL' emblem	\$ 50.40	NEC ✓
10	Tailgate inner trimboard	\$ 489.00	X
11	Tailgate lock	\$ 264.00	DMC ✓
12	Tailgate weatherstrip	\$ 391.00	*NEC ✓
13	Taillamp LH	\$ 389.00	SCR ✓
14	Taillamp corner garnish LH	\$ 157.00	?
15	Taillamp corner garnish support LH	\$ 32.80	?
	SUB TOTAL	\$ 5,849.20	
	Less 25%	\$ 1,462.30	
	SUB TOTAL	\$ 4,386.90	
	SPECIAL NET ITEM		
1	Rear bumper clips	\$ 60.00	30 NEC
2	Tailgate inner trimboard clips	\$ 60.00	X
3	Rear number plate	\$ 50.00	X
4	Rear windscreen glass sealant	\$ 50.80.00	*NEC
5	Sticker '70km/h'	\$ 15 20.00	NEC
6	Reverse sensor	\$ 300.00	200 DMC
	SUB TOTAL	\$ 570.00	
	LABOUR		
	Labour to remove & refit affected portion	\$ 1,000.00	300 600
	Spray paint on the affected portion	\$ 800.00	400
	Labour to remove & refit tailgate components	\$ 100.00	X 60
	Labour to remove & refit rear windscreen glass	\$ 200.00	50 120
	Labour to remove & refit reverse sensors	\$ 100.00	X 50
	To conduct wiring check	\$ 50.00	30
	To apply anti rust coating	\$ 100.00	20 30
	SUB TOTAL	\$ 2,350.00	
	GRAND TOTAL	\$ 7,306.90	