



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4968R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRT BUMPER COVER	DEFORMED	481.10	481.10
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRT BUMPER UPPER CENTRE MOULDING	NOT NECESSARY	368.50	-
1	FRT BUMPER SIDE BRACKET LH	NOT NECESSARY	28.00	-
1	HEADLAMP LH	CUT	2,110.30	2,110.30
1	FRT BUMPER SIDE MOULDING LH	NOT NECESSARY	93.60	-
1	DAYLIGHT RH	NOT NECESSARY	642.50	-
	LESS 20% DISCOUNT		-749.20	-522.68
			2,996.80	2,090.72
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		400.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	CHECK ALL LIGHTING.		60.00	30.00
			760.00	630.00
	<b>GRAND TOTAL</b>		<b>3,756.80</b>	<b>2,720.72</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>2,200.00</b>

Report Ref No. NS/INC23003967/Tvp3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.