

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 5985A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT DOOR ASSY LH	TO REPAIR SEE LABOUR	2,707.70	-
1	HEADLAMP ASSY LH	CUT	1,388.00	1,388.00
1	FENDER FENDER LH	TO REPAIR SEE LABOUR	663.00	-
1	BONNET	BENT	2,508.80	2,508.80
1	SIDE MIRROR LH	BROKEN	670.00	670.00
1	FRT WINDSCREEN PILLAR LH	TO REPAIR SEE LABOUR	894.35	-
	LESS 20% DISCOUNT		-1,766.37	-913.36
			7,065.48	3,653.44
	SPECIAL NETT ITEMS			
1	FRT DOOR COMFORT LOGO (SN)	NECESSARY	75.00	75.00
1	SEALANT (SN)	NOT NECESSARY	46.00	-
			121.00	75.00
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRT DOOR ASSY LH, FENDER FENDER LH AND FRT WINDSCREEN PILLAR LH.		1,200.00	560.00
	SPRAYPAINT.		1,200.00	1,000.00
	WIRING CHARGES.		50.00	30.00
	TUFF KOTE.		50.00	30.00
	REMOVE/REFIX FRT WINDSCREEN GLASS120.	NOT NECESSARY	120.00	-
	REMOVE/REFIX DOOR PARTS.	NOT NECESSARY	120.00	
			2,740.00	1,620.00
	GRAND TOTAL		9,926.48	5,348.44





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,250.00
(TO ITS PRE-ACCIDENT CONDITION)		·
(CONFIRMED)		

Report Ref No. NS/INC23003969/Tqp3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser