

ASS. REC. BY: Taught

REF:

INC

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHA 7746 K Yr Regn: 2019 May
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Traxi / Prime Mover /
 Truck / Trailer or
 Make: Plymouth c.c. 1580
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 413844 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KMH C851CVK4145903
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65R15
 R: 195/65R15
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Wesfah.
 Front: _____ Rear: _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 17/4/23
 Survey held at Comp & Logg
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: _____

1) _____
 Date/Time, File Return to?

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:	
Transportation:	
\$ + RS. SI	
Photos	
Others	
TOTAL	

Rep. Format: _____

Lump Sum / L.B.I. / _____

REPAIR ESTIMATE

Model : IONIQ(G3)

MVA: MS. LOKE YY

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Langhin'c / Hunterdon

Date:

Workshops

205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286

Date/Time: 17.04.2023 14:58

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5893373

JC NO305551245

CUSTOMER

MR/MS COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
TEL (R) 65508755 (O)

DISCOUNT CARD NO.

REGN NO:

SHA7746K

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....

MODEL

IONIQ(G2)

15.04.2023 19:20

DATE/TIME IN

YR OF MANU

03.05.2019

TARGET DATE

CHASSIS CODE

KMHC851CVKU145903

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 15.04.2023

NATURE: 3P 15.04.2023

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Knowledge Slip

me:

No.: SHA7746K YY
hicle No.:

me of Service Advisor

Signature/Date

be returned to Service Reception upon collection

Exit Pass

Vehicle No.: SHA7746K

Name of Service Advisor

Date

To be kept by Security Guard