

CL APPRAISER PTE LTD

Blk 416 Pasir Ris Dr 6 #08-235, Singapore 510416
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

INVOICE

Muhammad Nasiruddin Bin Mohd Khalid
C/o: ESL Automotive Pte Ltd
25 Kaki Bukit Road 4
#07-47 & #07-75 Synergy@KB, Singapore 417800

Invoice No. : CL/220535
Ref No. : ESL/10/2201/TP
Date : 26 October 2022

DESCRIPTION	AMOUNT
OUR SERVICE FEE CHARGES:	
<ul style="list-style-type: none">SURVEY INSPECTION FOR VEHICLE NO. <u>SJS 3093 T</u>RESURVEY INSPECTIONDIGITAL PHOTOGRAPHS SERVICES (<i>INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS</i>)TRANSPORTATION	
GRAND TOTAL	S\$ 623.00

E & O. E

Notes / Payment method:

All cheque payment should be "Crossed" and made payable to "CL APPRAISER PTE LTD"

Bank Transfer -

Account Name : CL APPRAISER PTE LTD

Account Number : 588041152001

Bank : OCBC

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd

ESL APPRAISER PTE LTD

Blk 416 Pasir Ris Dr 6 #08-235, Singapore 510416
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Muhammad Nasiruddin Bin Mohd Khalid
C/o: ESL Automotive Pte Ltd
25 Kaki Bukit Road 4
#07-47 & #07-75 Synergy@KB, Singapore 417800

Date : 26 October 2022
Our ref : ESL/10/2201/TP

Accident Date : 12 October 2022
Inspection Date : 17 October 2022
Repairer Name : ESL Automotive Pte Ltd
25 Kaki Bukit Road 4
#07-47 & #07-75 Synergy@KB, Singapore 417800

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No	: SJS 3093 T	Year / Capacity	: 2009 / 1499 cc
Make / Model	: Mitsubishi Lancer	Colour	: Grey
Chassis No	: JMYSRCY2A9U004437	Mileage	: 241369
Engine No	: 4A910124592		

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Habilead	225/40 R18	5 mm	Sport
Front Offside	: Habilead	225/40 R18	5 mm	Sport
Rear Nearside	: Habilead	225/40 R18	5 mm	Sport
Rear Offside	: Habilead	225/40 R18	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 103 copies

REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$6,100.00** on a contractual basis.

Under normal circumstances, the repair period would be about 8 (Eight) working days.

SL APPRAISER PTE LTD

Vehicle Registration No.: SJS 3093 T

Our Ref No.:

ESL/10/2201/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Rear boot lid	Damage	\$ 725.00	\$ 725.00	
2	Rear boot hinges	Intact	\$ 144.00		Xm
1	Rear boot inner trim	Damage	\$ 158.00	\$ 158.00	
2	Rear boot lamps	Damage	\$ 372.00	\$ 372.00	
1	Rear boot lock	Damage	\$ 68.00	\$ 68.00	
1	Rear boot rubber	Necessary	\$ 142.00	\$ 142.00	
1	Rear boot third brake lamp	Intact	\$ 126.00		Xm
2	Rear taillamps 2450 each	Damage	\$ 970.00	\$ 970.00	900
1	Rear bumper	Damage	\$ 785.00	\$ 785.00	710
2	Rear bumper brackets	Damage	\$ 130.00	\$ 130.00	
2	Rear bumper reflectors @ 35 each	Damage	\$ 90.00	\$ 90.00	70
1	Rear bumper reinforcement	Damage	\$ 225.00	\$ 225.00	210
2	Rear bumper side retainers	Necessary	\$ 97.00	\$ 97.00	
1	Rear bumper tow hook cover	Damage	\$ 38.00	\$ 38.00	
1	Rear bumper beam	Damage	\$ 105.00	\$ 105.00	85
1	Rear end panel	Damage	\$ 558.00	\$ 558.00	XR
1	Rear end panel inner garnish	Damage	\$ 145.00	\$ 145.00	
1	Rear floor panel	Repair	\$ 955.00		Xm
			\$ 5,833.00	\$ 4,608.00	3850
		Less 10%	\$ 583.30	\$ 460.80	
	Total Cost - List Items		\$ 5,249.70	\$ 4,147.20	3465

SPECIAL NETT ITEMS

1	Rear boot top spoiler	Necessary	\$ 280.00	\$ 280.00	
1	Rear boot inner trim clip (1 set)	Necessary	\$ 38.00	\$ 38.00	20
1	Rear bumper clip (1 set)	Necessary	\$ 50.00	\$ 50.00	30
1	Rear number plate with holder	Damage	\$ 50.00	\$ 50.00	45
1	Rear reverse sensor (1 set)	Damage	\$ 350.00	\$ 350.00	200
1	Rear reverse camera	Damage	\$ 450.00	\$ 450.00	300
	Total Cost - Special Nett items		\$ 1,218.00	\$ 1,218.00	875

Total cost of parts

\$ 6,467.70 \$ 5,365.20

SLC L APPRAISER PTE LTD

Vehicle Registration No.: SJS 3093 T

Our Ref No.:

ESL/10/2201/TP

S/No	Description	Repairer's Estimate	Revised Amount
------	-------------	---------------------	----------------

Total cost of parts c/f \$ **6,467.70** \$ **5,365.20**

LABOUR

1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ 50.00	30
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 120.00	\$ 80.00	60
3	To remove and refit rear reverse sensor and camera.	\$ 150.00	\$ 120.00	60
4	To transfer boot lid mechanism and wiring assembly to assist repair.	\$ 80.00	\$ 80.00	60
5	To apply undercoating on repaired and replaced panel.	\$ 100.00	\$ 60.00	30
6	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,200.00	\$ 1,000.00	700
7	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,050.00	\$ 880.00	700

GRAND TOTAL

\$ 9,247.70 \$ 7,635.20

5980
 4/\$4750
 06 days*

Vehicle Registration No.: SJS 3093 T

Our Ref No.: ESL/10/2201/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 6,100.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD

Cheong K. H
Automotive Appraiser