

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/III23003973/UQY3E2  
**Date:** 30/06/2023REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D22MPC0009204
<b>Claimant Vehicle No :</b>	SMY9336L	<b>Insured Vehicle No :</b>	SMN6415U
Date of Loss:	13/04/2023	Nature of Claim:	TP
		Claim No:	MPC2023D0004399

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMY9336L</b>		
Make & Model:	SSANGYONG KORANDO, 1.5 G DLX 6AT 2WD ESP E6 (A)	Engine No:	17595002067074
Reg. Date:	30/03/2021 (Man. Year: 2020)	Chassis No:	KPT70A1YSMP050007
Colour:	Black	Odometer:	48149 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Nexen 7 mm	Rear Left Side:	Nexen 7 mm
Front Right Side:	Nexen 7 mm	Rear Right Side:	Nexen 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>16,200.00</b>		
<b>(S\$)</b>	0.00	16,200.00	-16,200.00	
<b>+ GST 8.00/8.00% (S\$)</b>	0.00	1,296.00	-1,296.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>17,496.00</b>	<b>-17,496.00</b>	

INSPECTION

Date of Assignment:	17/04/2023		
Date Inspected:	18/04/2023	Inspected At:	Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36 Singapore 417883
Estimated Period of Repair:	10.0 days		

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 30 Jun 2023)	
Parts:	N/A	SSANGYONG KORANDO 1.5 G DLX 6AT 2WD ESP E6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMY9336L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**