



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ETHOZ GROUP LTD 30 BUKIT BATOK CRESCENTSINGAPORE 658075			Ref: CS/TP23003975/Uwy3e2	Date: 12/05/2023
			Code: TP274	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	JTG 8944	Veh. Inspected	YP 2763M	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	18/04/2023	
2. Vehicle Particulars & Condition				
Make & Model	ISUZU FRR90	c.c	5193	
Engine No.	4HK1281996	Year of Reg.	2016	
Chassis No.	JALFRR907E7000442	Colour	WHITE	
Odometer	263562 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	9.5 R17.5	GITI	6 mm	
L/H Front Tyre	9.5 R17.5	GITI	6 mm	
R/H Rear Tyre	9.5 R17.5 (D)	GITI	6/6 mm	
L/H Rear Tyre	9.5 R17.5 (D)	GITI	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/02/2023	Inspection Date	18/04/2023	
Survey held at	ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	