

Vehicle Damage Assessment Report for [GBL1582T]

Estimate Created: 05/06/2023 13:17 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 05/06/2023 13:24 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGo	Claim Number	CDMCG23000912
Claim Type	OD		
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number	

Vehicle Information

Brand	Toyota	Model	Hiace
Engine Type			
License Plate Number	GBL1582T	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK: CONCLUDED THE COST OF REPAIR AT \$3,191.50 WITH 7 WORKING DAYS	Insurlogic 4 (05/06/2023 13:24)
--	---------------------------------

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Rear fender panel (outer) right		1	800.00	10.00 %	880.00
Rear fender panel outer roller rail bar - RH		1	190.00	10.00 %	209.00
Rear rim hub cap - RH		1	75.00	10.00 %	82.50

Parts Subtotal 1,171.50

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
Panel beating	RnR	1400.00	0.00 %	1,400.00
To check wiring	RnR	20.00	0.00 %	20.00

Repair

Description	Severity	Cost	Markup/Disc %	Price
Rear fender panel (inner) RH	Medium	0.00	0.00 %	0.00
Rear wheel house panel (outer) RH	Medium	0.00	0.00 %	0.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	600.00	0.00 %	600.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 1,420.00

Paint Labor Subtotal 600.00

Labor Subtotal 2,020.00

Summary

Repair Cost 3,191.50

Discount(0 %) (0.00)

3,191.50

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 3,191.50