

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG23003989/WQY3M4
Date: 31/05/2023

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002662653
Claimant Vehicle No :	SML5915K	Insured Vehicle No :	FBJ7963Z
Date of Loss:	16/04/2023	Nature of Claim:	TP
		Claim No:	311699

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML5915K	Engine No:	3A92UHT1972
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AKH001867
Reg. Date:	28/05/2019 (Man. Year: 2019)	Odometer:	203781 km
Colour:	Silver		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Farroad 6 mm	Rear Left Side:	Farroad 6 mm
Front Right Side:	Farroad 6 mm	Rear Right Side:	Farroad 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,020.59	1,727.32	3,293.27	65.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,860.00	1,420.00	1,440.00	50.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,880.59	3,147.32	4,733.27	60.06
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	7,880.59	2,500.00	5,380.59	68.28
+ GST 8.00/8.00% (S\$)	630.45	200.00	430.45	68.28
Nett Amount (S\$)	8,511.04	2,700.00	5,811.04	68.28

INSPECTION

Date of Assignment:	25/04/2023		
Date Inspected:	18/04/2023	Inspected At:	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934
Estimated Period of Repair:	4.0 days		

Adjuster: Mohdakid**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 May 2023)	
Parts:	N/A	MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML5915K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Damaged	814.20 FL	*708.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Not Necessary	59.80 FL	*- FL
3	1		*REAR BUMPER REFLECTOR (N/S)	Scratched	96.00 FL	*52.00 FL
4	1		*REAR BUMPER LOWER GARNISH	Bent	419.30 FL	*419.30 FL
5	2		*REAR BUMPER BRACKET	Not Necessary	318.20 FL	*- FL
6	1		*END PANEL	Repair	562.30 FL	*- FL
7	1		*END PANEL KEYLESS SENSOR	Broken	110.00 FL	*110.00 FL
8	1		*END PANEL TOP GARNISH	Not Necessary	104.74 FL	*- FL
9	1		*TAILLAMP (N/S)	Broken	317.40 FL	*277.00 FL
10	1		*TAILLAMP SEALER	Necessary	20.00 FL	*20.00 FL
11	1		*REAR FENDER INNER TRIM	Not Necessary	363.40 FL	*- FL
12	1		*REAR FENDER	Repair	832.25 FL	*- FL
13	1		*BOOTLID	Repair	953.30 FL	*- FL
14	1		*BOOTLID WEATHERSTRIP	Not Necessary	170.00 FL	*- FL
15	1		*BOOTLID EMBLEM	Necessary	47.15 FL	*47.15 FL
16	1		*BOOTLID EMBLEM -ATTRAGE	Necessary	35.30 FL	*35.30 FL
17	1		*BOOTLID EMBLEM - MIVEC	Necessary	43.60 FL	*43.60 FL
18	1		*BOOTLID OUTER GARNISH	Scratched	159.30 FL	*159.30 FL
19	1		*REAR FENDER AIR VENT	Not Necessary	103.50 FL	*- FL
20	1		*REAR WINDSCREEN MOULDING	Not Necessary	46.00 FL	*- FL
21	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
22	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	30.00 FS	*- FS
23	1		*SET REAR REVERSE SENSOR	Damaged/Shorted	200.00 FS	*200.00 FS
24	1		*JOINT SEALANT	Not Necessary	150.00 FS	*- FS
25	1		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,135.74	2,101.65
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,115.15	374.33
Total Parts (\$\$)	5,020.59	1,727.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	New	60.00	30.00
2	REMOVE,REFIT REAR LINING, TRIM AND GARNISH	New	200.00	50.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	40.00
4	REMOVE AND RENEW REAR WINDSCREEN	New	150.00	0.00
5	TRANSFER PARTS, ATTACHMENT FROM BOOTLID TO NEW	New	150.00	0.00
6	PANEL BEATING ON AFFECTED AREAS	New	1,000.00	700.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	600.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	0.00
Gross Labour Cost (S\$)			2,860.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >