

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 4585B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILLAMP RH	CRACKED	247.00	247.00
1	REAR FENDER RH (NPA)	NOT NECESSARY	-	-
	LESS 10% DISCOUNT		-24.70	-24.70
			222.30	222.30
	<u>LABOUR</u>			
	LABOUR TO FACILITATE REPAIR.		300.00	200.00
	TO RESPRAY AFFECTED AREAS.		300.00	200.00
			600.00	400.00
	GRAND TOTAL		822.30	622.30

RECOMMENDED COST OF REPAIRS 622.30

Report Ref No. CS/TP23003993/Tqy3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A
Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.