

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 8391Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR SIDE PANEL L/H (CONSISTENT)	BENT	800.00	800.00
	LESS 10% DISCOUNT		-	-80.00
			800.00	720.00
	<u>LABOUR</u>			
	LABOUR CHARGES FOR KNOCKING, WELDING WORK, REMOVE & REFIT NEW PARTS & PAINTING.		600.00	550.00
			600.00	550.00
	GRAND TOTAL		1,400.00	1,270.00

RECOMMENDED COST OF LUMP SUM REPAIRS		1,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/HSB23003998/Knp3m4

KONG SENG CHEONG

Licensed Appraiser