

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT HSBC LIFE (SINGAPORE) PTE LTD CS3/HSB23003999/Wqp3e2 Ref: 10 MARINA BOULEVARD Date: 26/05/2023 #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 Code: HSB ATTN: LOH CYNTHIA Policy Particulars :- (THIRD PARTY CLAIM) 1. **SHA 1810Y GBB 4736A** Insured Veh. Veh. Inspected VFX/P2419138 0.00 Policy No. Coverage (\$) S3M04LPQ 0.00 Claim No. Excess (\$) LOH CYNTHIA 18/04/2023 **Assign Date** Assign From 2. **Vehicle Particulars & Condition** KIA 2900L 2902 Make & Model C.C **HIDDEN** Engine No. Year of Reg. 2009 KNCSE014297385008 WHITE Chassis No. Colour Odometer 262875 KM IN ORDER Steering **IN ORDER** NIL Modification **Brakes** GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre GREEN MAX 195 R15 7 mm L/H Front Tyre 195 R15 GREEN MAX 7 mm 155 R12 **GREEN MAX** 7 mm R/H Rear Tyre L/H Rear Tyre 155 R12 **GREEN MAX** 7 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** Inspect Date / Time 15/04/2023 26/04/2023 (10:00 AM) **Accident Date** Survey held at YEO & PARTNER 74 SUNGEI KADUT ST 1 SINGAPORE 729374 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000 5b. **Estimate Days of Repair**

Report Ref No. CS3/HSB23003999/Wqp3e2

Inspected By

Asst. Automotive Assessor

MUHAMMAD AKID BIN MOHAMED KAMAL

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

SEON And a Committee of OAE I become a famous become

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

4 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser