PROMINENT APPRAISER SERVICES PTE LTD Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191 Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No.: PAS/TP/0561122 Date of Report : 22/12/2022

To: Ms Angeline Ang Li Ling Mrs Angeline Fu Guo Ming Date of Assignment : 29/11/2022

C/o. 48 Toh Guan Road East
#01-119 Enterprise Hub

Report requested by : Ms Angeline Ang Li Ling Mr
Date of Accident : 29/11/2022

Singapore 608586 Date of Inspection : 29/11/2022 Claim No. : Third Party Claim

Claim No. : Third : Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SFX39S Engine Capacity (cc) : 1797

Make & Model: Toyota Prius Alpha (Hybrid)Mileage (km): 78441kmDate of Registration: 19/06/2018Chassis / Frame No.: ZVW400027613

Colour : Met. Silver Engine No. : 2ZR0A42754

TYRE CONDITION

Front LH : 6 mm Front RH : 6 mm

Make : Yokohama Make : Yokohama

Rear LH : 6 mm Rear RH : 6 mm

Make : Yokohama Make : Yokohama

Road wheels Type: Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable

Footbrake : Serviceable Steering : Serviceable

Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Gold Autoworks Pte Ltd

48, Toh Guan Road East, #01-119, Enterprise Hub, Singapore 608586

ASSESSMENT

Repairer's Estimate : \$ 15,305.65 Revised Amount : \$ 12,421.98

Less Excess : \$

Recommended Reserve : \$ 9,940.00 (Lump Sum)

Estimated Normal Period of Repairs : 8 Working Days

<u>Disclaimer:</u> The information contained in this report is intended for exclusive use of the addresses (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may protected by legal privileged. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg 201404434D

Vehicle No: SFX39S

Report No.: PAS/TP/0561122

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Gold Autoworks Pte Ltd, 48, Toh Guan Road East, #01-119, Enterprise Hub, Singapore 608586.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the rear portion.

DAMAGES

The tailgate, rear bumper, rear end panel, rear floor panel, rear chassis members, rear fenders, rear windscreen, taillamps, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$12,421.98.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$9,940.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd

Andrew How

Automobile Appraiser

MSAAA

Licensed Appraiser

PROMINENT APPRAISER SERVICES PTE LTD Qualified Loss Adjusters And Motor Appraisers Correspondence Mail Address: My Mail Box 886259 Singapore 919191 Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com Business Reg. 201404434D

Vehicle No: SFX39S

Report No.: PAS/TP/0561122

APPRAISEMENT SCHEDULE

S/No	. Qty	Parts Descriptions	Condition				Repairer's			Our
						F	Estimate (SS) As	sess	ment (S\$)
1	1 pc	Tailgate	Dented/Distorted							
2	1 pc	Tailgate windscreen	Broken/Shattered					1177	18	1,283.40
3		Tailgate windscreen moulding			DANS TEST		1,138.20)	\$	1,138.20 >
4	2 pcs	Tailgate windscreen dam kit		S	36.50		73.00)	\$	73.00 V
5	1 pc	Tailgate wiper blade	Necessary Dented	S	22.30	5)	\$	44.60 V
6	1 pc	Tailgate wiper motor				8		ř	S	43.90 V
7	1 pc	Tailgate no plate garnish	Dented/Jammed			8		nn	\$	656.80
8		Tailgate no.plate lamp R/L	Dented/Cracked	152		5			\$	393.20
9	1 pc	Tailgate emblem (Logo)	LH Cracked	\$	64.30	5			S	64.30
10	1 pc	Tailgate emblem (Prius A)	Necessary			S	98.40		\$	98.40
11	1 pc	Tailgate emblem (Hybrid)	Necessary			S	72.20		\$	72.20 🗸
12	1 pc	Tailgate inner trim	Necessary			\$	69.20		\$	69.20 🗸
13		Tailgate inner trim clip	Dented/Cracked			\$	476.90		\$	476.90 🗸
14		Tailgate lock assy	Necessary	\$	3.20	\$	32.00	15 ✓	\$	32.00
15		Tailgate weatherstrip	Dented/Jammed			\$		360 🗸		412.70
16		Taillamp R/L	Torn/Necessary			\$	335.10	•	\$	335.10 🗸
17			Cracked/Broken	\$	667.70	\$	1,335.40		\$	1,335.40 🗸
18	1 pc	Rr bumper (w/col.)	Dented			\$	1,220.90	823 v		1,220.90
19		Rr bumper reflector R/L	Refit	\$	56.90	\$	113.80	nn	\$	- X
20		Rr bumper clip	Necessary	\$	3.20	\$	19.20		\$	19.20 🗸
		Rr bumper retainer R/L	Cracked/Necessary	\$	92.30	S	184.60		\$	184.60 🗸
21		Rr fender RH	Dented/Repair			\$	4 2 2 2 2 2 2	nn	\$	- X
22		Rr trough panel R/L	RH Dented	\$	252.10	\$	504.20		\$	252.10 ×
23	2 pcs	Rr fender inner trim R/L	Cracked/Deformed	\$	668.80	\$	1,337.60		\$	1,337.60 X
24		Rr fender inner trim clip R/L	Necessary	S	3.20	\$	38.40	10.10	\$	38.40 X
25		Rr end panel	Dented			\$	625.50		\$	625.50 🗸
26		Rr end panel trim	Dented/Deformed			\$	232.10		\$	
27		Rr compartment cover	Dented/Cracked			\$	783.20			232.10 🗸
28	l pc l	Rr compartment storage center	Cracked/Deformed			\$	394.80			783.20
29	l pc l	Rr compartment storage RH	Cracked/Deformed			\$	131.60		S	394.80
30		Rr floor panel	Dented/Repair			\$	842.20	(12	8	131.60 X
31		Rr fender R/L	Dented/Repair			φ				- X
32		Rr trough panel LH	Dented/Repair				(Dafa	labour	10.	4, 7 & 8)
33		Rr floor panel	Dented/Repair				(Refer	labour i	10. 4	4, 7 & 8)
34	2 pcs F	Rr chassis member R/L	Dented/Repair				(Refer	labour i	10, 4	1, 7 & 8)
			8362.50			100				1, 7 & 8)
			-25%				14,034.20	9	5 11	1,749.30
			6074.07		scount: 25%	6 \$	3,508.55	25% 9	5 2	2,937.33
			List	Parts Sub	-Total:	\$	10,525.65	5	8	3,811.98
1		r windscreen sealant	Necessary		S/N	6	50.00			
2	1 pc R	r windscreen solar film	Affected/Necessary			S	50.00	5		40.00 🗸
		Pashcam (i-Drive il 1)	Rr Cam Missing		S/N	\$	250.00	00 🗸 🖇		250.00
		r no.plate (w/bracket)	Dented/Cracked		S/N	\$	300.00	\$		300.00 🗸
		r reverse camera	Refit		S/N	\$		10 🗸 s		50.00
		r reverse sensor			S/N	\$		nn \$		×
		r end panel sealant	Dented/Damaged		S/N	S	200.00	\$		200.00 🗸
		Pares sessimit	Necessary		S/N	\$	50.00 3	0 🗸 🖇		40.00
			Special	Man C 1	The state of the s	\$	1,150.00	-		

710

Parts Total:

\$ 11,675.65

\$ 9,691.98



MINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers
Correspondence Mail Address: My Mail Box 886259 Singapore 919191 Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SFX39S			Report No. : PAS/TP/0561122					
S/No	. Labour Descriptions	Repairer's Estimate (S\$)		Our Assessment (S\$)				
2	To remove and reinstall electrical wiring system for necessary repairs. To check rear electrical wiring system. To install rear windscreen to new tailgate.	\$ \$	60.00 120.00	s s	50.00 120.00			
3	To transfer tailgate component parts to new tailgate. (Include transfer reverse camera, tailgate spoiler & supply sealant/adhesive tape)	S	150.00	\$	120.00	50		
4	To remove and reinstall rear interior trims, garnishes, seats, etc. for necessary repairs.	\$	120.00	\$	80.00	50		
5	To vacuum, clean up broken glass debris. To provide cleaning service on interior trimm and leather seats.	ing \$	100.00	\$	80.00	30		
6	To remove, replace and reinstall rear reverse sensors & control unit.	\$	50.00	\$	50.00	30		
7	To straighten, repair, realign on affected area and replace damaged parts.	\$	1,500.00	\$	1,100.00	100		
8	To spray painting, blending on affected and adjacent area.	\$	1,500.00	\$	1,100.00	800		
9	To spray anti-rust coating on new and affected panels. 2140	\$	30.00	\$	30.00	/		
	Labour Total:	\$	3,630.00	\$	2,730.00			
	Total (Parts & Labour):	\$	15,305.65	\$	12,421.98			
	7 days	21.8	7					

/ days

For Lump Sum Repairs

L/S - 7297.49 = 7300

The final adjusted Lump Sum contract amount is \$

Under normal circumstances, the repairs should be completed within a reasonable period

8 Working Days. (Exclude waiting days of PRI, Sunday, Pubic Holiday and awaiting of shipment for spare parts)

104 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.