

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/GRB23002510/WVY3M4-1**Date:** 08/05/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447\_02  
**Claimant Vehicle No :** SNG5258M **Insured Vehicle No :** SMV6090E  
 Date of Loss: 03/03/2023 Nature of Claim: TP Claim No: MFL2023D0002915

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNG5258M**  
 Make & Model: MERCEDES-BENZ E200 SPORT, 2.0 M-HYBRID (A) Engine No: 26492030488112  
 Reg. Date: 13/08/2022 (Man. Year: 2022) Chassis No: W1K2130802B046597  
 Colour: Black Odometer: 28725 km  
 Engine Capacity: 1991 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35 R19 Rear Tyre Size: 245/40 R19  
 Front Left Side: Bridgestone 6 mm Rear Left Side: LAUFENN 6 mm  
 Front Right Side: Bridgestone 6 mm Rear Right Side: LAUFENN 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	47,347.76	17,435.19	29,912.57	63.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,600.00	3,250.00	7,350.00	69.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>57,947.76</b>	<b>20,685.19</b>	<b>37,262.57</b>	<b>64.30</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>16,500.00</b>		
<b>Nett Amount (\$\$)</b>	<b>57,947.76</b>	<b>16,500.00</b>	<b>41,447.76</b>	<b>71.53</b>

INSPECTION

Date of Assignment: 09/03/2023  
 Date Inspected: 09/03/2023 Inspected At: RS GARAGE SERVICES PTE LTD  
 BLK 8 KAKI BUKIT AVE 4  
 #02-24 SINGAPORE 415875  
 Estimated Period of Repair: 0.0 days

**Adjuster:** Mohdakid**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 08 May 2023)
<b>Parts:</b>	143	MERCEDES-BENZ E200 SPORT 2.0 M-HYBRID (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SNG5258M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	1,500.00 FL	*1,316.78 FL
2	1		*FRONT BUMPER SIDE RETAINER	Deformed/Cracked	68.36 FL	*68.36 FL
3	2		*FRONT BUMPER SENSOR	2Pc Malfunction	791.64 FL	*395.82 FL
			4 PIECES			
4	6		*FRONT BUMPER SENSOR RING	Necessary	38.10 FL	*38.10 FL
5	6		*FRONT BUMPER SENSOR HOLDER	Necessary	110.16 FL	*110.16 FL
6	1		*FRONT BUMPER SPONGE	Cracked/Deformed	200.00 FL	*186.69 FL
7	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	558.01 FL	*- FL
8	1		*FRONT BUMPER TOP RUBBER	Serviceable	300.00 FL	*- FL
9	1		*FRONT BUMPER INNER CENTRE GARNISH	Serviceable	400.00 FL	*- FL
10	1		*FRONT HEADLAMP	Cracked	4,000.00 FL	*3,520.82 FL
11	1		*FRONT HEADLAMP CONTROL UNIT	Not Necessary	692.71 FL	*- FL
12	1		*FRONT HEADLAMP TOP PANEL	Not Necessary	171.55 FL	*- FL
13	1		*FRONT FENDER	Dented	1,200.00 FL	*797.00 FL
14	1		*FRONT FENDER INNER SHIELD	Not Necessary	181.76 FL	*- FL
15	1		*FRONT RIM	Dented	900.00 FL	*779.44 FL
16	1		*FRONT SHOCK ABSORBER	Not Necessary	900.00 FL	*- FL
17	1		*FRONT KNUCKLE ARM	Not Necessary	1,800.00 FL	*- FL
18	1		*FRONT KNUCKLE ARM BEARING	Warped	700.00 FL	*548.21 FL
19	1		*FRONT UPPER ARM	Not Necessary	1,000.00 FL	*- FL
20	1		*FRONT LOWER ARM	Not Necessary	800.00 FL	*- FL
21	1		*FRONT SPRING LINK ARM	Not Necessary	1,000.00 FL	*- FL
22	1		*FRONT STABILIZER BAR	Not Necessary	706.21 FL	*- FL
23	1		*FRONT STABILIZER BAR LINK	Not Necessary	115.68 FL	*- FL
24	1		*FRONT DOOR	Scratched	2,500.00 FL	*2,144.85 FL
25	1		*FRONT DOOR LOCK	Not Necessary	432.21 FL	*- FL
26	1		*FRONT DOOR INNER TRIM BOARD	Not Necessary	1,692.31 FL	*- FL
27	1		*FRONT DOOR WEATHER STRIP	Serviceable	400.00 FL	*- FL
28	1		*FRONT DOOR GLASS	Not Necessary	400.00 FL	*- FL
29	1		*FRONT DOOR GLASS OUTER MOULDING	Serviceable	400.00 FL	*- FL
30	1		*FRONT DOOR GLASS REGULATOR GEAR	Not Necessary	690.71 FL	*- FL
31	1		*FRONT DOOR GLASS REGULATOR MOTOR	Not Necessary	1,149.21 FL	*- FL
32	1		*REAR DOOR	Scratched	2,500.00 FL	*2,387.06 FL
33	1		*REAR DOOR LOCK	Serviceable	500.00 FL	*- FL
34	1		*REAR DOOR INNER TRIM BOARD	Cracked	2,000.00 FL	*1,325.00 FL
35	1		*REAR DOOR WEATHER STRIP	Serviceable	400.00 FL	*- FL
36	1		*REAR DOOR GLASS OUTER MOULDING	Serviceable	400.00 FL	*- FL
37	1		*REAR DOOR GLASS REGULATOR GEAR	Serviceable	800.00 FL	*- FL
38	1		*REAR DOOR GLASS REGULATOR MOTOR	Serviceable	1,200.00 FL	*- FL
39	1		*REAR FENDER	Repair	2,500.00 FL	*- FL
40	1		*REAR FENDER INNER TRIM	Not Necessary	1,140.91 FL	*- FL
41	1		*REAR FENDER SIDE SHIELD	Not Necessary	215.31 FL	*- FL
42	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	500.00 FL	*- FL
43	1		*REAR RIM	Scratched	900.00 FL	*779.44 FL
44	1		*REAR SHOCK ABSORBER	Not Necessary	583.24 FL	*- FL
45	1		*REAR KNUCKLE ARM	Not Necessary	2,000.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*REAR KNUCKLE ARM BEARING	Warped	500.00 FL	*480.41 FL
47	1		*REAR UPPER ARM	Not Necessary	528.31 FL	*- FL
48	1		*REAR TRAILING ARM	Not Necessary	601.31 FL	*- FL
49	1		*REAR LOWER ARM	Serviceable	257.91 FL	*- FL
50	1		*REAR ADJUSTABLE ARM	Serviceable	241.71 FL	*- FL
51	1		*REAR BUMPER	Cracked	2,500.00 FL	*1,800.00 FL
52	1		*REAR BUMPER SIDE RETAINER	Broken	78.46 FL	*78.46 FL
53	1		*REAR BUMPER SENSOR	1Pc Malfunction	729.92 FL	*182.48 FL
		4 PIECES				
54	6		*REAR BUMPER SENSOR RING	Necessary	38.10 FL	*38.10 FL
55	6		*REAR BUMPER SENSOR HOLDER	Necessary	110.16 FL	*110.16 FL
56	1		*TAILLAMP	Cracked	900.00 FL	*739.18 FL
57	1		*SET FRONT BUMPER CLIPS	Cracked/Deformed	80.00 FS	*30.00 FS
58	1		*FRONT TYRE	Cut	500.00 FS	*350.00 FS
59	1		*SET FRONT FENDER INNER SHIELD CLIPS	Cracked/Deformed	80.00 FS	*30.00 FS
60	1		*SET FRONT GRILLE CLIPS	Not Necessary	80.00 FS	*- FS
61	1		*SET FRONT DOOR INNER TRIM BOARD CLIPS	Cracked/Deformed	80.00 FS	*30.00 FS
62	1		*SET REAR DOOR INNER TRIM BOARD CLIPS	Cracked/Deformed	80.00 FS	*30.00 FS
63	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
64	1		*SET REAR FENDER SIDE SHIELD CLIPS	Cracked/Deformed	80.00 FS	*30.00 FS
65	1		*SET REAR WINDSCREEN GLASS SEALANT	Not Necessary	100.00 FS	*- FS
66	1		*SET REAR WINDSCREEN GLASS SPONGE	Not Necessary	80.00 FS	*- FS
67	1		*SET REAR WINDSCREEN GLASS CLIPS	Not Necessary	80.00 FS	*- FS
68	1		*REAR TYRE	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>49,743.96</b>	<b>18,326.52</b>
<b>- List Item Discount on L Items 5.00/5.00% (\$\$)</b>	2,396.20	891.33
<b>Total Parts (\$\$)</b>	<b>47,347.76</b>	<b>17,435.19</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT ALL FITTINGS TO FRONT RH DOOR TO FACILITATE THE REPAIR	New	150.00	60.00
2	TO REMOVE, RENEW AND REFIT FRONT SENSOR TO FACILITATE THE REPAIR	New	200.00	60.00
3	TO CHECK THE WIRING SYSTEM TO FACILITATE THE REPAIR AND REFIT THE SAME (FRONT)	New	100.00	30.00
4	DIAGNOSTIC & RESET FAULT CODE	New	300.00	100.00
5	TO CONDUCT A WATER LEAKAGE TEST (FRONT)	New	50.00	0.00
6	TO SPRAY ANTI-RUST ON ACCIDENT-AFFECTED PANEL (FRONT)	New	100.00	30.00
7	TO CONDUCT WHEEL ALIGNMENT (BEFORE AND AFTER)	New	200.00	80.00
8	TO REMOVE, RENEW AND REFIT THE FRONT UNDERCARRIAGE TO FACILITATE THE REPAIR	New	600.00	80.00
9	TO CONDUCT WHEEL BALANCING TO FACILITATE THE REPAIR (FRONT) }	New	50.00	30.00
10	TO REMOVE, RENEW AND REFIT TYRE TO FACILITATE THE REPAIR (FRONT) }	New	50.00	0.00
11	TO REMOVE, RENEW AND REFIT ALL ACCIDENT-DAMAGED PARTS. CUT, WELD, PANEL BEAT, AND STRAIGHTEN ALL ACCIDENT DAMAGE AREAS AND FIT THE ABOVE SAME	New	1,500.00	600.00
12	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT-AFFECTED AREAS	New	1,500.00	600.00
13	TO REMOVE AND REFIT ALL FITTINGS TO REAR RH DOOR TO FACILITATE THE REPAIR	New	150.00	60.00
14	TO REMOVE, RENEW AND REFIT FRONT SENSOR TO FACILITATE THE REPAIR	New	200.00	60.00
15	TO CHECK THE WIRING SYSTEM TO FACILITATE THE REPAIR AND REFIT THE SAME (REAR)	New	100.00	30.00
16	TO REDO THE SEALANT ON THE GAP TO FACILITATE THE REPAIR	New	100.00	0.00
17	TO CONDUCT A WATER LEAKAGE TEST (REAR)	New	100.00	0.00
18	TO SPRAY ANTI-RUST ON ACCIDENT-AFFECTED PANEL (REAR)	New	100.00	60.00
19	TO REMOVE, RENEW AND REFIT ALL ACCIDENT-DAMAGED PARTS. CUT, WELD, PANEL BEAT AND STRAIGHTEN ALL ACCIDENT DAMAGE AREAS AND FIT THE ABOVE SAME	New	2,500.00	600.00
20	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT-AFFECTED AREAS	New	1,500.00	600.00
21	TO REMOVE AND REFIT UPHOLSTERY,CARPETS, AND REAR FENDER INNER TRIMS TO FACILITATE THE REPAIR	New	300.00	60.00
22	TO REMOVE, RENEW AND REFIT THE REAR UNDERCARRIAGE TO FACILITATE THE REPAIR	New	300.00	80.00
23	TO CONDUCT WHEEL BALANCING TO FACILITATE THE REPAIR }	New	50.00	30.00
24	TO REMOVE, RENEW AND REFIT TYRE TO FACILITATE THE REPAIR }	New	50.00	0.00
25	TO REMOVE, AND REFIT THE FUEL TANK ASSY TO FACILITATE THE REPAIR	New	150.00	0.00
26	TO REMOVE, RENEW AND REFIT THE REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR	New	200.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>10,600.00</b>	<b>3,250.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >