

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIS23004008/RPA3Q2**Date:** 26/06/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2004218717
Claimant Vehicle No :	SKP8895S	Insured Vehicle No :	SNJ3933U
Date of Loss:	14/04/2023	Nature of Claim:	TP
		Claim No:	202332007387

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP8895S		
Make & Model:	VOLKSWAGEN GOLF, 1.4 TSI (A7) (5G13GZ)	Engine No:	CXS220492
Reg. Date:	20/10/2014 (Man. Year: 2014)	Chassis No:	WVWZZZAUZFW067652
Colour:	Grey	Odometer:	135141 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,258.29	6,032.97	2,225.32	26.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,790.00	6,550.00	4,240.00	39.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,048.29	12,582.97	6,465.32	33.94
+ GST 8.00/8.00% (S\$)	1,523.86	1,006.64	517.22	33.94
Nett Amount (S\$)	20,572.15	13,589.61	6,982.54	33.94
+ Car Rental (7.0 x S\$100.00/day + 8.00% GST) (S\$)		756.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		14,372.36		

INSPECTION

Date of Assignment:	18/04/2023	
Date Inspected:	20/04/2023	Inspected At: Volkswagen Group Singapore Pte Ltd 247 ALEXANDRA ROAD Singapore 159934
Estimated Period of Repair:	7.0 days	

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jun 2023)
Parts:	144	VOLKSWAGEN GOLF 1.4 TSI (A7) (5G13GZ) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKP8895S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TRUNK LID	Bent	2,390.18 FS	*2,390.18 FS
2	1		*1K WINDOW ADHESIVE (2 PCS)	Necessary	91.31 FS	*91.31 FS
3	1		*ALL PURPOSE CLEANER	Necessary	76.20 FS	*76.20 FS
4	1		*PRIMER	Necessary	22.42 FS	*22.42 FS
5	1		*ACTIVATOR	Necessary	19.46 FS	*19.46 FS
6	1		*APPLICATOR (2 PCS)	Necessary	16.54 FS	*16.54 FS
7	1		*HOOD LATCH SATIN BLACK BOOT LID LOCK	Not Necessary	243.01 FS	*- FS
8	1		*WATER DRAIN HOSE	Not Necessary	9.01 FS	*- FS
9	2		*GROMMET	Not Necessary	31.50 FS	*- FS
10	1		*WEBBING ADHESIVE TAPE	Not Necessary	42.26 FS	*- FS
11	1		*GASKET WETHERSTRIP	Not Necessary	272.60 FS	*- FS
12	1		*INSCRIPTION BRIGHT CHROME NAME PLATE -GOLF	Necessary	81.76 FS	*81.76 FS
13	1		*INSCRIPTION PURE WHITE/PO NAME PLATE-BLUEMOTION	Necessary	93.43 FS	*93.43 FS
14	1		*INSCRIPTION CHROME SHINE/NAME PLATE -TSI	Necessary	94.75 FS	*94.75 FS
15	1		*ADDITIONAL BRAKE LIGHT WI 3RD BRAKELIGHT	Necessary	169.11 FS	*169.11 FS
16	1		*TAILLIGHT TAILLIGHT INNER LH	Not Necessary	298.71 FS	*- FS
17	1		*TRIM PANEL FOR HATCH GATE BOOT LID TRIM COVER	Not Necessary	198.03 FS	*- FS
18	1		*COVER FOR BUMPER PRIMED	Cracked	1,297.16 FS	*1,297.16 FS
19	1		*REAR DIFFUSOR SATIN BLACK	Cut	328.99 FS	*328.99 FS
20	1		*RIVET (4 PCS)	Necessary	4.75 FS	*4.75 FS
21	1		*BUMPER REINFORCEMENT	Bent	733.15 FS	*733.15 FS
22	1		*ATTACHMENT STRIP BUMPER CTR BRACKET	Chipped	76.87 FS	*76.87 FS
23	1		*GUIDE PIECE LHR BUMPER BRACKET (UPPER)	Not Necessary	46.66 FS	*- FS
24	1		*GUIDE PIECE RHR BUMPER BRACKET (UPPER)	Cracked	46.66 FS	*45.50 FS
25	1		*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Not Necessary	45.50 FS	*- FS
26	1		*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Not Necessary	45.50 FS	*- FS
27	2		*LICENSE PLATE LIGHT	Not Necessary	81.02 FS	*- FS
28	1		*FLAT CONTACT HOUSING WITH NUMBER PLATE LIGHT WIRE HOUSING (2 PCS)	Cut	22.77 FS	*11.39 FS
29	1		*REFLECTOR LH	Not Necessary	77.18 FS	*- FS
30	1		*END PLATE END PANEL	Repair	222.30 FS	*- FS
31	6		*WELD STUD	Not Necessary	6.86 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
32	1		*ZINC SPRAY	Not Necessary	68.22 FS	*- FS
33	1		*2K-BODY ADHESIVE	Not Necessary	458.32 FS	*- FS
34	1		*SEALANT CAN BE SPRAYED	Not Necessary	66.10 FS	*- FS
35	1		*REAR NUMBER PLATE	Bent	80.00 FS	*80.00 FS
36	1		*REVERSE SENSOR	Shorted	400.00 FS	*400.00 FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$)	8,258.29 6,032.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	4,320.00	2,160.00
2	SPRAY PAINT	New	3,400.00	2,040.00
3	R&R REAR W/SCREEN	New	720.00	720.00
4	TRANSFER BOOT LID MECHANISM	New	720.00	360.00
5	R&R REAR LUGGAGE TRIM	New	720.00	360.00
6	REAR WATER LEAK TEST	New	150.00	150.00
7	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
8	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
Gross Labour Cost (S\$)			10,790.00	6,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >