

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS1/AIS23004027/TVP3M4**Date:** 22/05/2023**REFERENCE**

Insured/Claimant: COMFORTDELGRO BUS PTE LTD Policy No: SP2003452035
Date of Loss: 30/01/2023 Nature of Claim: OD Claim No: 202332005032

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PD1018H**
Make & Model: ZHONG TONG LCK6126EVG, (A) Engine No: 0
Reg. Date: 22/12/2022 (Man. Year: 2022) Chassis No: LDYEC5231N0026054
Colour: White Odometer: 0 km
Engine Capacity: 0 cc
Market Value/New Car Price: S\$820,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: Rear Tyre Size:
Front Left Side: 8 mm Rear Left Side: 8 mm
Front Right Side: 8 mm Rear Right Side: 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,095.00	8,910.00	5,185.00	36.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,960.00	2,580.00	1,380.00	34.85
Paintwork Labour	1,200.00	1,000.00	200.00	16.67
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,255.00	12,490.00	6,765.00	35.13
- Excess (\$\$)	4,500.00	4,500.00	0.00	0.00
(\$\$)	14,755.00	7,990.00	6,765.00	45.85
+ GST 8.00/8.00% (\$\$)	1,180.40	639.20	541.20	45.85
Nett Amount (\$\$)	15,935.40	8,629.20	7,306.20	45.85

INSPECTION

Date of Assignment: 18/04/2023
Date Inspected: 19/04/2023 Inspected At: Connect 3 (WOODLANDS) (HQ)
566 Woodlands Road (Mandai Estate)
Singapore 728697
Estimated Period of Repair: 12.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 May 2023)	
Parts:	N/A	ZHONG TONG LCK6126EVG (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PD1018H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH SIDE 2ND EXIT DOOR RH OUTER RUBBER MOULDING	Cut	860.00 F	*860.00 F
2	1		*LH SIDE 2ND EXIT DOOR RH INNER RUBBER MOULDING	Cut	730.00 F	*730.00 F
3	1		*LH 2ND EXIT DOOR LH & RH LOWER DOOR PANEL	N/S Repair/ O/S Bent	1,160.00 F	*580.00 F
4	1		*LH 2ND EXIT DOOR UPPER LAMP	Not Necessary	235.00 F	*- F
5	1		*LH SIDE GLASSES	N/S Cracked/ O/S Not Necessary	3,200.00 F	*1,600.00 F
6	1		*LH SIDE GLASS FRAME	Bent	985.00 F	*985.00 F
7	1		*LH SIDE LOWER PANEL (OUTER)	N/S Bent/ O/S Repair	2,500.00 F	*1,250.00 F
8	1		*LH SIDE HANDICAP OUTER DOOR SWITCH	Distorted	360.00 F	*360.00 F
9	1		*LH SIDE EMERGENCY OPEN DOOR SWITCH	Distorted	400.00 F	*400.00 F
10	2		*LH SIDE LAST DOOR OUTER RUBBER MOULDING LH & RH	Cut	1,720.00 F	*1,720.00 F
11	2		*LH 2ND DOOR AND LAST DOOR UPPER LINKAGE (STEEL)	Not Necessary	760.00 F	*- F
12	1		*REFLECTOR LAMP	Cut	185.00 F	*185.00 F
13	1		*LH REAR TYRE	Not Necessary	680.00 F	*- F
14	1		*SEALANT 8PIECES	Necessary (6Pieces Only)	320.00 FS	*240.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **14,095.00** **8,910.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	SPRAY PAINTING.	New	1,200.00	1,000.00
Labour Items				
2	LABOUR TO REMOVE LH 2ND & LAST EXIT DOOR TO ASSIST REPAIR.	New	600.00	450.00
3	LABOUR TO REMOVE & REFIT LH SIDE GLASSES TO ASSIST REPAIR.	New	600.00	450.00
4	TRANSFER LH 2 DOORS FITTINGS.	New	500.00	0.00
5	WHEEL ALIGNMENT & BALANCING.	New	180.00	0.00
6	LABOUR CHARGES.	New	1,800.00	1,500.00
7	WIRING FOR 2 EXIT DOORS & 2 DOOR OUTER SWITCH.	New	280.00	180.00
Gross Labour Cost (S\$)			5,160.00	3,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >