

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI23004043/KNP3Q2**Date:** 28/04/2023**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MS011884		
Claimant Vehicle No :	SHF621G	Insured Vehicle No :	GBD5236J		
Date of Loss:	14/04/2023	Nature of Claim:	TP	Claim No:	M2302514

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHF621G	Engine No:	2ZR2G96958
Make & Model:	TOYOTA PRIUS, 1.5 (A)	Chassis No:	JTDKB3FU203092063
Reg. Date:	12/03/2021 (Man. Year: 2020)	Odometer:	150889 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Wanli 7 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Wanli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,400.72	1,776.73	2,623.99	59.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,420.00	470.00	4,950.00	91.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,820.72	2,246.73	7,573.99	77.12
+ GST 8.00/8.00% (S\$)	785.66	179.74	605.92	77.12
Nett Amount (S\$)	10,606.38	2,426.47	8,179.91	77.12

INSPECTION

Date of Assignment:	20/04/2023	Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
Date Inspected:	18/04/2023	Inspected At: 2, Ang Mo Kio Street 63
Estimated Period of Repair:	2.0 days	Singapore 569111

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Apr 2023)
Parts:	144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHF621G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Buckled	558.39 FL	*558.39 FL
2	1		*COVER ,REAR BUMPER LOWER	Serviceable	19.43 FL	*- FL
3	1		*GUARD,REAR BUMPER CENTER	Dented/ Cut	726.92 FL	*726.92 FL
4	1		*SEAL ,REAR BUMPER SIDE ,LH	Serviceable	111.41 FL	*- FL
5	1		*SEAL ,REAR BUMPER SIDE ,RH	Serviceable	111.41 FL	*- FL
6	1		*FILLER ,REAR BUMPER EXTENSION ,RH	Serviceable	155.72 FL	*- FL
7	1		*FILLER ,REAR BUMPER EXTENSION ,LH	Serviceable	155.72 FL	*- FL
8	1		*RETAINER ,REAR BUMPER SIDE,LH	Serviceable	147.11 FL	*- FL
9	1		*RETAINER ,REAR BUMPER SIDE,RH	Serviceable	148.58 FL	*- FL
10	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Bent	419.90 FL	*419.90 FL
11	1		*COVER ,FLOOR UNDER ,RH	Serviceable	220.50 FL	*- FL
12	1		*COVER ,FLOOR UNDER ,LH	Serviceable	304.92 FL	*- FL
13	1		*COVER,REAR FLOOR	Cracked	290.43 FL	*290.43 FL
14	1		*COVER ,DECK TRIM REAR	Serviceable	159.39 FL	*- FL
15	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Serviceable	824.46 FL	*- FL
16	1		*SET PARKING AID	Dented	700.00 FS	*220.00 FS
17	1		*REAR BUMPER CLIP	Necessary	65.00 FS	*60.00 FS
18	1		*REAR LH BUMPER RETAINER CLIP	Not Necessary	65.00 FS	*- FS
19	1		*REAR RH BUMPER RETAINER CLIP	Not Necessary	65.00 FS	*- FS
20	1		*END PANEL INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
21	1		*REAR BUMPER PROTECTOR	No such part	180.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	5,489.29 2,275.64
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,088.57 498.91
					Total Parts (\$\$)	4,400.72 1,776.73

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	600.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	220.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,000.00	200.00
4	TO TRANSFER OF TAILGATE FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
6	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
7	TO TRANSFER OF TAILGATE FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
8	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$\$)			5,420.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >