



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 4842P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER	DEFORMED	506.00	506.00
1	FRONT BUMPER FOGLAMP LH	CRACKED	305.00	305.00
1	FRONT BUMPER FOGLAMP LH GARNISH (BLACK)	DEFORMED	88.00	88.00
1	FRONT BUMPER FOGLAMP LH OUTER MOULDING (SILVERY)	DEFORMED	90.00	90.00
1	FRONT BUMPER LOWER GRILLE (BLACK)	CUT	168.00	168.00
1	FRONT BUMPER LOWER LID (BLACK)	CUT	506.00	506.00
1	FRONT BUMPER LOWER SPOILER (SILVERY)	TO REPAIR SEE LABOUR	175.00	-
1	FRONT BUMPER NOZZLE JACK LH	CRACKED	196.00	196.00
1	FRONT BUMPER NOZZLE JACK LH BRACKET	CRACKED	48.00	48.00
1	FRONT BUMPER NOZZLE JACK LH COVER	MISSING	25.00	25.00
2	FRONT BUMPER PARKING SENSOR @\$176.00	DAMAGED (1PC ONLY)	352.00	176.00
4	FRONT BUMPER PARKING SENSOR HOLDER @\$20.00	NECESSARY	80.00	80.00
2	FRONT BUMPER PARKING SENSOR O-RING @\$18.00	NOT NECESSARY	36.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	493.00	-
2	FRONT BUMPER SIDE RETAINER L/R @\$28.00	NOT NECESSARY	56.00	-
1	FRONT BUMPER SPONGE	CRACKED	105.00	105.00
1	FRONT LH HEADLAMP	CRACKED	2,369.00	2,369.00
1	FRONT SUPPORT PANEL	NOT NECESSARY	662.00	-
	LESS 10% DISCOUNT		-626.00	-466.20
			5,634.00	4,195.80
<b>SPECIAL NETT ITEMS</b>				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	FRONT BUMPER NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	FRONT BUMPER NUMBER PLATE HOLDER (SN)	NOT NECESSARY	50.00	-
1	RADIATOR COOLANT (SN)	NOT NECESSARY	80.00	-
			235.00	30.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO REMOVE, REINSTALL AIR CON PARTS, VACUUMS, REFILL AIR CON GAS. (TO FR)	NOT NECESSARY	120.00	-
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING. (TO FR)		80.00	80.00
	TO RESET SYSTEM AFTER REPAIR WORKS.	NOT NECESSARY	400.00	-
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	400.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT BUMPER LOWER SPOILER (SILVERY).		1,000.00	400.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	30.00
			2,720.00	910.00
	<b>GRAND TOTAL</b>		<b>8,589.00</b>	<b>5,135.80</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,100.00</b>

Report Ref No. CS/AGI23004045/Any3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.