



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMM 6157U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BOOT LID	DENTED/BENT	752.50	752.50
1	REAR BOOT "H" LOGO	NECESSARY	89.50	89.50
1	REAR BOOT EMBLEM "I-VTEC"	NECESSARY	48.60	48.60
1	REAR BOOT LAMP - LH	CRACKED	189.60	189.60
2	REAR BOOT OUTER GARNISH	CUT/CRACKED	221.80	221.80
1	REAR BOOT INNER LOCK	NOT NECESSARY	230.80	-
1	REAR BOOT W/STRIP	NOT NECESSARY	182.60	-
1	REAR BUMPER	DISTORTED	683.60	617.20
1	REAR BUMPER TOW COVER - LH	TORN	12.60	12.60
2	REAR BUMPER PDC SENSORS @ 287.60	MALFUNCTION (1PC ONLY)	575.20	180.00
1	REAR BUMPER PDC SENSOR WIRE HARNESS	TORN	261.20	261.20
1	REAR BUMPER REINFORCEMENT	BENT	395.60	188.00
2	REAR BUMPER SIDE RETAINERS - L/R @ 55	N/S CRACKED/ O/S NOT NECESSARY	110.00	30.00
2	REAR BUMPER SIDE HOLDERS - L/R @ 48.10	N/S CRACKED/ O/S NOT NECESSARY	96.20	32.00
1	REAR BUMPER SIDE COVER - LH	SCRATCHED	86.90	86.90
1	REAR BUMPER REFLECTOR - LH	NOT NECESSARY	62.60	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	552.80	-
1	REAR FENDER AIR VENT - LH	NOT NECESSARY	86.50	-
1	REAR FENDER INNER SHIELD - LH	NOT NECESSARY	126.20	-
1	REAR TAILLAMP - LH	CRACKED	381.60	321.10
1	REAR TAILLAMP PANEL - LH	TO REPAIR SEE LABOUR	155.60	-
LESS 20% DISCOUNT			-1,060.40	-606.20
			4,241.60	2,424.80
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	45.00	30.00
1	REAR BUMPER DIFUSSER (SN)	TORN	550.00	480.00
1	SET REAR BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-

Report Ref No. CS/GAI23004048/Uny3m4



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST TAIL PIPE - LH (SN)	NOT NECESSARY	350.00	-
			990.00	510.00
	<b>LABOUR</b>			
	TO CHECK REAR ELECTRICAL WIRING.		50.00	20.00
	TO REMOVE, REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR.		120.00	80.00
	TO REMOVE, REFIX REAR EXHAUST SYSTEMS.	NOT NECESSARY	120.00	-
	TO RESPRAY UNDERCOATING.		100.00	40.00
	TO RESPRAY PAINTING AND ETC.		1,200.00	900.00
	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR TAILLAMP PANEL - LH.		1,200.00	580.00
			2,790.00	1,620.00
<b>GRAND TOTAL</b>			<b>8,021.60</b>	<b>4,554.80</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,600.00</b>

Report Ref No. CS/GAI23004048/Uny3m4

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.