

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897**Our File No:** CS/AIS23004050/WNP3E2**Date:** 05/05/2023REFERENCE

Insured/Claimant: WELDANPOWER ENTERPRISES &amp; ENGINEERING SERVICES PTE

Policy No: AIS/2022/0000375/001315

Date of Loss: 13/04/2023

Nature of Claim: OD

Claim No: 202332007297

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **YP8202B**

Make &amp; Model: HINO XZU710R-HKFMS3, 4.0 D (M)

Engine No: N04CUS35534

Reg. Date: 28/12/2017 (Man. Year: 2017)

Chassis No: JHHUCS3H00K023379

Colour: White

Odometer: 308767 km

Engine Capacity: 4009 cc

Market Value/New Car Price: S\$73,000.00

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 7.00 R16

Rear Tyre Size: 7.00 R16

Front Left Side: West Lake 6 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	
<b>- Excess (S\$)</b>	0.00	2,700.00	-2,700.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>-2,700.00</b>	<b>2,700.00</b>	

INSPECTION

Date of Assignment: 19/04/2023

Date Inspected: 19/04/2023 Inspected At:

160 Sin Ming Drive, #03-03, Sin Ming AutoCity  
Singapore 575722  
Repairer: Cheng Auto Bodyworks

Estimated Period of Repair: 5.0 days

**Adjuster:** Mohdakid**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 05 May 2023)	
<b>Parts:</b>	N/A	HINO XZU710R-HKFMS3 4.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for YP8202B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER		-	-
2	1		*LH FRONT BUMPER BRACKET		-	-
3	1		*LH FRONT BUMPER FOG LAMP		-	-
4	1		*LH FRONT BUMPER FOG LAMP BRACKET		-	-
5	1		*HEADLAMP LH C/W MOTOR		-	-
6	1		*FRONT GRILLE		-	-
7	1		*FRONT GRILLE LOGO		-	-
8	1		*LH FRONT CORNER PANEL		-	-
9	1		*FRONT PANEL		-	-
10	1		*FRONT WINDSCREEN GLASS		-	-
11	1		*FRONT WINDSCREEN GLASS MOULDING - TOP		-	-
12	1		*FRONT WINDSCREEN GLASS MOULDING - LOWER		-	-
13	1		*LH FRONT WINDSCREEN GLASS MOULDING - LOWER		-	-
14	1		*FRONT WINDSCREEN GLASS SEALANT		-	-
15	1		*FRONT WINDSCREEN GLASS DAMPING SEAL		-	-
16	1		*LH FORNT WIPER ARM CAP COVER		-	-
17	1		*LH FORNT WIPER BLADE		-	-
18	1		*LH WING MIRROR - BIG		-	-
19	1		*LH WING MIRROR - ROUND		-	-
20	1		*LH WING MIRROR - STAY		-	-
21	1		*LH WING MIRROR - INNER COVER		-	-
22	1		*LH WING MIRROR - CAP COVER		-	-
23	1		*LH FRONT DOOR		-	-
24	1		*LH FRONT DOOR STEP GARNISH		-	-
25	1		*LH FRONT DOOR STEP GARNISH REFLECTOR		-	-
26	1		*LH FRONT DOOR SIGNAL LAMP		-	-
27	1		*LH FRONT DOOR VERTICAL OUTER GARNISH		-	-
28	1		*LH FRONT DOOR OUTER MOULDING		-	-
29	1		*LH FRONT DOOR GLASS		-	-
30	1		*LH FRONT DOOR GLASS RUN CHANNEL		-	-
31	1		*LH FRONT DOOR OUTER PULL HANDLE		-	-
32	1		*LH FRONT DOOR TOP HINGES		-	-
33	1		*LH FRONT DOOR CHECKER		-	-
34	1		*LH FRONT DOOR INNER TRIMBOARD		-	-
35	1		*LH FRONT DOOR INNER SPEAKER		-	-
36	1		*LH FRONT DOOR WEATHERSTRIP		-	-
37	1		*LH FRONT DOOR LOWER WHEEL ARCH GARNISH		-	-
38	1		*LH FRONT DOOR SPLASH SHIELD		-	-
39	1		*AIR CON CONDENSER		-	-
40	1		*AIR CON DISCHARGE PIPE		-	-
41	1		*AIR CON LIQUID PIPE		-	-
42	1		*SIDE GATE RUBBER STPPER		-	-

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*SIDEGATE LOWER SAFETY GUARD		-	-
44	1		*LH FRONT WHEEL RIM		-	-
45	1		*LH FRONT SHOCK ABSORBER		-	-
46	1		*LH FRONT KNUCKLE ARM		-	-
47	1		*LH FRONT KNUCKLE BEARING -BIG		-	-
48	1		*LH FRONT KNUCKLE BEARING - SMALL		-	-
49	1		*LH FRONT BEARING OIL SEAL		-	-
50	1		*LH FRONT LEAF SPRING SHACKLE		-	-
51	1		*LH FRONT LEAF SPRING SHACKLE PIN - CENTRE		-	-
52	1		*LH FRONT AXLE BEAM		-	-
53	1		*LH FRONT AXLE SECURING `U` BOLT		-	-
54	1		*FRONT TIE ROD END		-	-
55	1		*LH FRONT KING PIN LOCK		-	-
56	1		*LH REAR TYRE - OUTER		-	-
57	1		*LH REAR TYRE - INNER		-	-
58	1		*LH REAR WHEEL RIM		-	-
59	1		*LH REAR WHEEL HUB		-	-
60	1		*LH REAR WHEEL BEARING - BIG		-	-
61	1		*LH REAR WHEEL BEARING - SMALL		-	-
62	1		*LH REAR WHEEL BEARING OIL SEAL		-	-
63	1		*LH REAR SHOCK ABSORBER		-	-
64	1		*LH REAR AXLE SECURING `U` BOLT		-	-
65	1		*LH REAR LEAF SPRING SHACKLE		-	-
66	1		*LH REAR LEAF SPRING SHACKLE PIN (CENTRE)		-	-
67	1		*LH REAR AXLE SHAFT		-	-
68	1		*REAR AXLE OIL (3 LITRE)		-	-
69	1		*BRAKE FLUID (1 LITRE)		-	-
70	1		*LH REAR WHEEL MUDGUARD		-	-
71	1		*LH REAR WHEEL MUDGUARD BRACKET		-	-
72	1		*REAR REINFORCEMENT BEAM		-	-
73	1		*LH TAILLAMP		-	-
74	1		*LH TAILLAMP BRACKET		-	-
75	1		*REAR CARGO DECK SECURING `U` BOLT - FRONT		-	-
76	1		*LH FRONT TYRE		-	-
77	1		*ERP BRACKET		-	-
<b>Total Parts (\$\$)</b>					<b>0.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Paintwork Labour</u></b>				
1	TO SPRAY PAINTING	New	-	-
<b><u>Labour Items</u></b>				
2	TO TOW ACCIDENT VEHICLE FROM SCENE TO WORKSHOP	New	-	-
3	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS	New	-	-
4	TO REMOVE AND RENEW AIR CONDENSER, PIPES AND DRYER, VACCUUM AND TOP UP AIR CON GAS	New	-	-
5	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	-	-
6	TO REMOVE DOORS FITTINGS	New	-	-
7	TO DISMANTLE AND CHECK AND RENEW AFFECTED FRONT UNDERCARRIAGE	New	-	-
8	TO DISMANTLE AND CHECK AND RENEW AFFECTED REAR UNDERCARRIAGE	New	-	-
9	TO REMOVE, REALIGN REAR CARGO DECK	New	-	-
10	TO FOCUS HEADLAMP AND TAILLAMP, TO CHECK FRONT & REAR LIGHTING OPERATION AND REWIRING	New	-	-
11	TO CONDUCT WHEEL ALIGNMENT TEST	New	-	-
<b>Gross Labour Cost (\$)</b>			<b>0.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >