

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Reg. No. 19900/196R GST Reg. No. 19-900/196-R |  |  |                     |        |                       |  |
|---|--|--|---------------------|--------|-----------------------|--|
|   |  | Affiliated to Federation Internation                   | nale Des Experts En | Automo | bile                  |  |
|   | AUTO & GENERA  | L INSURANCE (S) PL                                     |                     | Ref:   | CS/AGI23004052/Wqy3e2 |  |
|   |  | INSURANCE)<br>U AVENUE #03-01<br>PPING CENTRESINGAPORE |                     | Date:  | 30/06/2023            |  |
|   |  |  |                     | Code:  | AGI                   |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM    |  |  |                     |        |                       |  |
|   | Insured Veh.   | SLH 3227J  | Veh. Inspected      |        | SJQ 1775H             |  |
|   | Policy No.   | P10796229R00   | Coverage (\$)       |        | 0.00                  |  |
|   | Claim No.  | C10021630 /SR  | Excess (\$)         |        | 0.00                  |  |
|   | Assign From  | FRAULEINE KHOO   | Assign Date         |        | 19/04/2023            |  |
| 2. Vehicle Particulars & Condition            |  |  |                     |        |                       |  |
|   | Make & Model   | SUZUKI SWIFT   | c.c                 |        | 1490                  |  |
|   | Engine No.   | HIDDEN   | Year of Reg.        |        | 2009                  |  |
|   | Chassis No.  | JSAEZC21S00551797                                      | Colour              |        | WHITE                 |  |
|   | Odometer   | 98291 KM   | Steering            |        | IN ORDER              |  |
|   | Brakes   | IN ORDER   | Modification        |        | STANDARD ALLOY RIM    |  |
|   | General  | GOOD   |                     |        |                       |  |
| 3.  | 3. Conditions of Tyres   |  |                     |        |                       |  |
|   |  | Size   | Make                |        | Balance               |  |
|   | R/H Front Tyre   | 185/60 R15   | YOKOHAMA            |        | 6 mm                  |  |
|   | L/H Front Tyre   | 185/60 R15   | YOKOHAMA            |        | 6 mm                  |  |
|   | R/H Rear Tyre  | 185/60 R15   | YOKOHAMA            |        | 6 mm                  |  |
|   | L/H Rear Tyre  | 185/60 R15   | YOKOHAMA            |        | 6 mm                  |  |
| 4.  | Description of Damages   |  |                     |        |                       |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.   |  |                     |        |                       |  |
|   | DAMAGES SEE DETAILS.   |  |                     |        |                       |  |
| 5.  | 5. General Information   |  |                     |        |                       |  |
|   | Accident Date  | 10/04/2023   | Inspection Date     | •      | 26/04/2023            |  |
|   | Survey held at 60 Jalan Lam Huat #05-06/07 Singapore 737869  |  |                     |        |                       |  |
|   | Repairer   | Repairer JAS AUTO SERVICES                             |                     |        |                       |  |
| 5a.   | Remarks  |  |                     |        |                       |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                     |        |                       |  |
| 5b.   |  | Estimate Days of Repair                                |                     |        |                       |  |
|   |  |  |                     |        |                       |  |

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: