

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23004056/TNP3Q2**Date:** 30/05/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00021372201

Claimant Vehicle No : SLK4521L **Insured Vehicle No :** SJU1762Z

Date of Loss: 18/04/2023 Nature of Claim: TP Claim No: SNM23D202862/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK4521L**

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A) Engine No: 3A92UDP1789

Reg. Date: 18/01/2017 (Man. Year: 2016) Chassis No: MMBSTA13AHH003738

Colour: Maroon Odometer: 119132 km

Engine Capacity: 1193 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	7,860.60	3,027.08	4,833.52	61.49	
Miscellaneous Items	0.00	0.00	0.00		
Labour	3,520.00	1,440.00	2,080.00	59.09	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	11,380.60	4,467.08	6,913.52	60.75	
Approved Total (Overridden) (S\$)		3,550.00			
	(S\$)	11,380.60	3,550.00	7,830.60	68.81
	+ GST 8.00/8.00% (S\$)	910.45	284.00	626.45	68.81
	Nett Amount (S\$)	12,291.05	3,834.00	8,457.05	68.81

INSPECTION

Date of Assignment: 20/04/2023

Date Inspected: 20/04/2023 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 30 May 2023)	
Parts:	N/A	mitsubishi attrage 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK4521L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	918.00 FL	*828.40 FL
2	1		*BOOTLID CENTRE EMBLEM	Necessary	53.00 FL	*53.00 FL
3	1		*BOOTLID ALTRAGE EMBLEM	Necessary	24.00 FL	*24.00 FL
4	1		*BOOTLID MIVEC EMBLEM	Necessary	47.00 FL	*47.00 FL
5	1		*BOOTLID CHROME MOULDING	Not Necessary	318.00 FL	*- FL
6	1		*SET BOOTLID CHROME MOULDING CLIPS	Not Necessary	60.00 FL	*- FL
7	1		*BOOTLID RH HINGE	Not Necessary	192.00 FL	*- FL
8	1		*BOOTLID LH HINGE	Not Necessary	192.00 FL	*- FL
9	1		*BOOTLID LOCK	Not Necessary	228.00 FL	*- FL
10	1		*BOOTLID LOCK CATCH	Not Necessary	68.00 FL	*- FL
11	1		*BOOTLID WEATHERSTRIP	Not Necessary	189.00 FL	*- FL
12	1		*REAR BUMPER	Deformed	704.00 FL	*704.00 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FL	*30.00 FL
14	1		*REAR BUMPER RH RETAINER	Cracked	34.00 FL	*34.00 FL
15	1		*REAR BUMPER LH RETAINER	Not Necessary	34.00 FL	*- FL
16	1		*REAR BUMPER LH REFLECTOR	Cracked	43.00 FL	*43.00 FL
17	1		*REAR BUMPER RH REFLECTOR	Cracked	43.00 FL	*43.00 FL
18	1		*LH TAILLAMP ASSY	Cracked	435.00 FL	*335.40 FL
19	1		*LH TAILLAMP PANEL	Not Necessary	102.00 FL	*- FL
20	1		*SET LH TAILLAMP LOCK CLIPS	Not Necessary	22.00 FL	*- FL
21	1		*RH TAILLAMP ASSY	Cracked	435.00 FL	*335.40 FL
22	1		*RH TAILLAMP PANEL	Not Necessary	102.00 FL	*- FL
23	1		*SET RH TAILLAMP LOCK CLIPS	Not Necessary	22.00 FL	*- FL
24	1		*END PANEL	Bent	455.00 FL	*455.00 FL
25	1		*END PANEL INNER GARNISH	Deformed	89.00 FL	*89.00 FL
26	1		*SET END PANEL INNER GARNISH CLIPS	Necessary	60.00 FL	*20.00 FL
27	1		*END PANEL AIR VENT	Not Necessary	43.00 FL	*- FL
28	1		*END PANEL AIR VENT COVER	Not Necessary	54.00 FL	*- FL
29	1		*END PANEL RH SIDE COVER	Not Necessary	28.00 FL	*- FL
30	1		*END PANEL ANTENNA SENSOR	Not Necessary	105.00 FL	*- FL
31	1		*END PANEL BUZZER SENSOR	Not Necessary	98.00 FL	*- FL
32	1		*LH REAR FENDER INNER TRIM BOARD	Not Necessary	234.00 FL	*- FL
33	1		*SET LH REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	70.00 FL	*- FL
34	1		*LH REAR FENDER SPLASH SHIELD	Not Necessary	57.00 FL	*- FL
35	1		*SET LH REAR FENDER SPLASH SHIELD CLIPS	Not Necessary	30.00 FL	*- FL
36	1		*RH REAR FENDER INNER TRIM BOARD	Not Necessary	234.00 FL	*- FL
37	1		*SET RH REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	70.00 FL	*- FL
38	1		*RH REAR FENDER SPLASH SHIELD	Not Necessary	57.00 FL	*- FL
39	1		*SET RH REAR FENDER SPLASH SHIELD CLIPS	Not Necessary	30.00 FL	*- FL
40	1		*SPARE TYRE PANEL MAT	Not Necessary	198.00 FL	*- FL
41	1		*SPARE TYRE PANEL TOP COVER	Not Necessary	339.00 FL	*- FL
42	1		*EXHAUST SILENCER	Not Necessary	602.00 FL	*- FL
43	1		*EXHAUST SILENCER GASKET	Not Necessary	36.00 FL	*- FL
44	1		*BOOTLID C&C EMBLEM	Necessary	80.00 FS	*50.00 FS
45	1		*END PANEL JOINT SEALANT	Necessary	80.00 FS	*40.00 FS
46	1		*SET REAR BUMPER REVERSE SENSOR	Not Working	350.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR NUMBER PLATE	Not Necessary	70.00 FS	*- FS
48	1		*REAR REVERSE CAMERA	Not Necessary	680.00 FS	*- FS
49	1		*RH TAILLAMP PANEL JOINT SEALANT	Not Necessary	45.00 FS	*- FS
50	1		*RH TAILLAMP PANEL JOINT SEALANT	Not Necessary	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,584.00	3,331.20
- List Item Discount on L Items 10.00/10.00% (\$)	723.40	304.12
Total Parts (\$)	7,860.60	3,027.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGED BODYPARTS .TO PANEL BEATING ,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,400.00	600.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,200.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	80.00	30.00
5	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	80.00	30.00
6	REMOVE AND REPLACE REAR INNER TRIMS,GARNISH AND BOARDS TO ASSIST REPAIR	New	250.00	60.00
7	REMOVE AND REPLACE EXHAUST SILENCER AND HANGERS TO ASSIST REPAIR	New	180.00	0.00
8	REMOVE AND REPLACE REAR REVERSE CAMERA TO ASSIST REPAIR	New	100.00	30.00
9	REMOVE AND REPLACE BOOTLID INNER COMPONENTS TO NEW BOOTLID	New	150.00	60.00
Gross Labour Cost (S\$)			3,520.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >