5/16/23, 12:45 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III23004063/WNY3M4

16/05/2023 Date:

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_03

Claimant Vehicle FBN7341Y Insured Vehicle No: GBJ8972R No:

Date of Loss: 12/04/2023 Nature of Claim: TP Claim No: MFL2023D0004073

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBN7341Y**

HONDA CB190X, 184cc WH161FMK18J00732 Make & Model: Engine No: Reg. Date: 06/12/2018 (Man. Year: 2018) Chassis No: LWBPCL1A4J1004052

Colour: Odometer: 118762 km Red

Engine Capacity: 184 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 140/70-R17 110/70-R17 Rear Tyre Size: Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		0.00	0.00	0.00	
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
N	ett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/04/2023

CHEK KONG MOTOR PTE LTD

387B YEW YEE INDUSTRIAL ESTATE Inspected At: Date Inspected: 20/04/2023

WOODLANDS ROAD

SINGAPORE 677948

Estimated Period of Repair: 0.0 days

HUEY YON Adjuster: Mohdakid Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

5/16/23, 12:45 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 09 May 2023)

Parts: N/A HONDA CB190X 184cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBN7341Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

5/16/23, 12:45 PM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >