

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/MSG23000032/RQY3M4-1**Date:** 15/05/2023REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 30001961291

**Claimant Vehicle No :** SJM386A**Insured Vehicle No :** SLP4138J

Date of Loss: 29/12/2022

Nature of Claim: TP

Claim No: 297287

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJM386A**

Make &amp; Model: TOYOTA ISIS, 1.8 LXA (A)

Engine No: 1ZZ3105959

Reg. Date: 18/12/2008 (Man. Year: 2008)

Chassis No: ZNM100054749

Colour: Blue

Odometer: 190560 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16

Rear Tyre Size: 215/60R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,809.40	1,969.07	5,840.33	74.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,100.00	970.00	2,130.00	68.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,909.40</b>	<b>2,939.07</b>	<b>7,970.33</b>	<b>73.06</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,350.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,909.40</b>	<b>2,350.00</b>	<b>8,559.40</b>	<b>78.46</b>

INSPECTION

Date of Assignment: 30/12/2022

Date Inspected: 04/01/2023 Inspected At:

Garage B Pte Ltd (HQ)

No. 1 Bukit Batok Cresnet, #05-55 WCEGA Plaza  
Singapore 658064

Estimated Period of Repair: 4.0 days

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2023)
Parts:	144	TOYOTA ISIS 1.8 LXA (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM386A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH HEADLAMP ASSY	Leg Bent/Cracked	672.00 FL	*672.00 FL
2	1		*LH HEADLAMP LOWER SUPPORT PANEL	Not Necessary	221.60 FL	*- FL
3	1		*FRONT BUMPER	Grazed/Scraped	1,117.20 FL	*788.00 FL
4	2		*FRONT BUMPER SIDE RETAINER LH/RH	Necessary	112.20 FL	*112.20 FL
5	1		*FRONT BUMPER FOG LAMP HOLE COVER LH	Dislodged/Missing	110.80 FL	*110.80 FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	369.10 FL	*369.10 FL
7	1		*LH FRONT WHEELHOUSE PANEL	Not Necessary	714.80 FL	*- FL
8	1		*LH FRONT FENDER	Repair	837.60 FL	*- FL
9	1		*LH FRONT FENDER SPLASH SHIELD	Not Necessary	184.60 FL	*- FL
10	1		*LH FRONT DRIVE SHAFT	Not Necessary	1,024.10 FL	*- FL
11	1		*LH FRONT SUSPENSION LOWER ARM	Not Necessary	405.00 FL	*- FL
12	1		*LH FRONT KNUCKLE ARM	Not Necessary	435.00 FL	*- FL
13	1		*LH FRONT KNUCKLE ARM BEARING	Not Necessary	218.10 FL	*- FL
14	1		*LH FRONT SHOCK ABSORBER	Not Necessary	417.80 FL	*- FL
15	1		*FRONT STABILISER BAR	Not Necessary	292.70 FL	*- FL
16	1		*LH FRONT STABILISER LINK	Not Necessary	140.00 FL	*- FL
17	1		*STEERING TIE ROD LH	Not Necessary	199.90 FL	*- FL
18	1		*STEERING TIE ROD END LH	Not Necessary	189.70 FL	*- FL
19	1		*STEERING RACK & PINION ASSY	Not Necessary	1,597.00 FL	*- FL
20	10		*FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
21	8		*LH FRONT FENDER SPLASH SHIELD CLIP	Not Necessary	40.00 FS	*- FS
22	1		*LH FRONT TYRE	Not Necessary	225.00 FS	*- FS
23	1		*LH FRONT SPORT RIM	Dented/Abraded	550.00 FS	*400.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	10,124.20 2,482.10
					- List Item Discount on L Items 25.00/25.00% (\$\$)	2,314.80 513.03
					Total Parts (\$\$)	7,809.40 1,969.07

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO DISMANTLE AND REMOVE DAMAGED PARTS, RENEW AND INSTALL; TO CUT OUT DAMAGED BODY PANEL, INSTALL AND WELD NEW PART; TO PULL, KNOCK, STRAIGHTEN AND RESHAPE AFFECTED AREAS	New	750.00	400.00
2	SPRAY PAINTING OF THE AFFECTED PARTS AND AREAS - FRONT BUMPER, FRONT FENDER, FRONT LH WHEELHOUSE PANEL, LH HEADLAMP LOWER BRACKET AND NECESSARY AREAS	New	1,000.00	400.00
3	TO CHECK ALL AFFECTED WIRING AND ELECTRICAL PARTS FOR CONDITION AND RECTIFY WHERE NEEDED	New	60.00	30.00
4	TO REALIGNMENT HEADLAMPS AND REFOCUS HEADLAMP BEAMS	New	90.00	20.00
5	TO REMOVE AND REPLACE THE DAMAGED STEERING RACK & PINION ASSY AND TO CENTRALISE STEERING WHEEL AFTER INSTALLATION	New	450.00	0.00
6	TO CHECK WHEEL ALIGNMENT FOR CONDITION BEFORE REPAIR	New	90.00	90.00
7	TO REMOVE AND REPLACE DAMAGED FRONT LEFT UNDERCARRIAGE AND SUSPENSION COMPONENTS	New	600.00	0.00
8	TO APPLY ANTI-RUST UNDERCOAT FOR THE AFFECTED AREAS	New	60.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>3,100.00</b>	<b>970.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >