



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS3/SPF22007193/Dwy3e2-1
ACCIDENT CLAIMS SECTION(SPORE POLICE FORCE)POLICE LOGISTICS BASE (PLB)1 HEMMANT ROADSINGAPORE 438675		Date:	27/04/2023
ATTN: HAFIZUL FARHAN		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBB 7823L	Veh. Inspected	GBC 3073E
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2022/045	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	19/04/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA 150	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	JTFAT35Y70K201787	Colour	SILVER
Odometer	294671 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15C	GOODYEAR	4 mm
L/H Front Tyre	195 R15C	GOODYEAR	4 mm
R/H Rear Tyre	195 R15C	GOODYEAR	4 mm
L/H Rear Tyre	195 R15C	GOODYEAR	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	25/07/2022	Inspection Date	28/07/2022
Survey held at	NGEE NGEE MOTOR BLK 1 NO: 22 PANDAN LOOP SINGAPORE 128219		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. A)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	