

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS6/AIS23004075/CVP3M4**Date:** 19/05/2023**REFERENCE**

Insured/Claimant: AUTOBAHN RENT A CAR PTE LTD Policy No: SPMF1000000542
Date of Loss: 13/04/2023 Nature of Claim: OD Claim No: ABRAISCL2023-00026

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMK4628B**
Make & Model: HONDA JAZZ, 1.3 CVT (A) Engine No: L13B14100944
Reg. Date: 11/04/2019 (Man. Year: 2019) Chassis No: JHMGK3850KS213785
Colour: White Odometer: 91010 km
Engine Capacity: 1318 cc
Market Value/New Car Price: S\$71,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15
Front Left Side: Falken Ziex 5 mm Rear Left Side: Falken Ziex 5 mm
Front Right Side: Falken Ziex 5 mm Rear Right Side: Falken Ziex 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,409.50	6,028.00	2,381.50	28.32
Miscellaneous Items	185.00	85.00	100.00	54.05
Labour	2,660.00	1,960.00	700.00	26.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,254.50	8,073.00	3,181.50	28.27
Approved Total (Overridden) (\$\$)		5,650.00		
- Excess (\$\$)	0.00	2,000.00	-2,000.00	
(\$\$)	11,254.50	3,650.00	7,604.50	67.57
+ GST 8.00/8.00% (\$\$)	900.36	292.00	608.36	67.57
Nett Amount (\$\$)	12,154.86	3,942.00	8,212.86	67.57

INSPECTION

Date of Assignment: 19/04/2023 Present Location: Ding Auto Pte Ltd (HQ)
Date Inspected: 20/04/2023 Inspected At: Ding Auto Pte Ltd (HQ)
Estimated Period of Repair: 6.0 days 176 Sin Ming Drive #04-06, Sin Ming Autocare
Singapore 575721

Adjuster: SIMON HO LEONG CHUAN**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 May 2023)
Parts:	144	HONDA JAZZ 1.3 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK4628B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Broken	520.00 F	*520.00 F
2	1		*FRONT BUMPER RETAINER RH (WCP)	Distorted	15.00 F	*15.00 F
3	1		*FRONT BUMPER RETAINER LH (WCP)	Not Necessary	15.00 F	*- F
4	1		*FRONT BUMPER SUPPORT (WCP)	Dented	185.00 F	*185.00 F
5	1		*FRONT BUMPER COVER (WCP)	No such part	170.00 F	*- F
6	1		*BONNET (WCP)	Buckled	320.00 F	*320.00 F
7	1		*BONNET HINGE RH (WCP)	Bent	35.00 F	*35.00 F
8	1		*BONNET HINGE LH (WCP)	Bent	35.00 F	*35.00 F
9	1		*BONNET LOCK (WCP)	Bent	85.00 F	*85.00 F
10	1		*BONNET INSULATOR (WCP)	Not Necessary	80.00 F	*- F
11	1		*BONNET STAND (WCP)	Not Necessary	30.00 F	*- F
12	1		*BONNET STAND HOOK (WCP)	Not Necessary	20.00 F	*- F
13	1		*BONNET FRONT SEAL (WCP)	Not Necessary	25.00 F	*- F
14	1		*BONNET UPPER END GARNISH (WCP)	Not Necessary	60.00 F	*- F
15	1		*FRONT GRILLE BASE (WCP)	Broken	240.00 F	*240.00 F
16	1		*FRONT GRILLE LOWER CHROME MLDG (WCP)	Cracked	165.00 F	*165.00 F
17	1		*FRONT GRILLE CTR LOWER TRIM (WCP)	Cracked	145.00 F	*145.00 F
18	1		*FRONT LOWER GRILLE (WCP)	Cracked	125.00 F	*125.00 F
19	1		*FRONT GRILLE CTR BRACKET (WCP)	Missing	25.00 F	*25.00 F
20	1		*FRONT GRILLE BADGE (WCP)	Missing	20.00 F	*20.00 F
21	1		*FRONT SUPPORT PANEL CPL (WCP)	Bent	390.00 F	*390.00 F
22	1		*FRONT SUPPORT UPPER GARNISH (WCP)	Not Necessary	30.00 F	*- F
23	1		*FRONT FENDER RH (WCP)	Buckled	185.00 F	*185.00 F
24	1		*FRONT FENDER LH (WCP)	Repair	185.00 F	*- F
25	1		*FRONT FENDER INNER SHIELD RH (WCP)	Not Necessary	80.00 F	*- F
26	1		*FRONT FENDER INNER SHIELD LH (WCP)	Not Necessary	80.00 F	*- F
27	1		*FRONT FENDER WHEELHOUSE REINF RH (WCP)	Not Necessary	140.00 F	*- F
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*WIPER GARNISH (WCP)	Not Necessary	190.00 F	*- F
29	1		*HEADLAMP ASSY RH (WCP)	Broken	440.00 F	*440.00 F
30	1		*HEADLAMP ASSY LH (WCP)	Cracked	440.00 F	*440.00 F
31	1		*HEADLAMP BRACKET RH (WCP)	Cracked	30.00 F	*30.00 F
32	1		*HEADLAMP BRACKET LH (WCP)	Not Necessary	30.00 F	*- F
33	1		*FOG LAMP COVER RH (WCP)	Missing	35.00 F	*35.00 F
34	1		*FOG LAMP COVER LH (WCP)	Not Necessary	35.00 F	*- F
35	1		*FRONT LOWER SIDE GARNISH RH (WCP)	Not Necessary	20.00 F	*- F
36	1		*FRONT LOWER SIDE GARNISH LH (WCP)	Not Necessary	20.00 F	*- F
37	1		*RADIATOR ASSY (WCP)	Cracked	620.00 F	*620.00 F
38	1		*RADIATOR AIR GUIDE RH (WCP)	Distorted	25.00 F	*25.00 F
39	1		*RADIATOR AIR GUIDE LH (WCP)	Distorted	25.00 F	*25.00 F
40	1		*CONDENSOR ASSY (WCP)	Dented	460.00 F	*460.00 F
41	1		*FAN SHROUD (WCP)	Cracked	90.00 F	*90.00 F
42	1		*FAN SHROUD - RADIATOR (WCP)	Cracked	90.00 F	*90.00 F
43	1		*FAN BLADE (WCP)	Cracked	45.00 F	*45.00 F
44	1		*FAN BLADE - RADIATOR (WCP)	Cracked	45.00 F	*45.00 F
45	1		*FAN MOTOR (WCP)	Shorted	220.00 F	*220.00 F
46	1		*FAN MOTOR - RADIATOR (WCP)	Shorted	220.00 F	*220.00 F
47	1		*A/C SUCTION HOSE (WCP)	Not Necessary	130.00 F	*- F
48	1		*A/C DISCHARGE HOSE (WCP)	Dented	140.00 F	*140.00 F
49	1		*WASHER TANK (WCP)	Dented	65.00 F	*65.00 F
50	1		*WASHER PUMP (WCP)	Not Necessary	55.00 F	*- F
51	1		*AIR DUCT (WCP)	Not Necessary	45.00 F	*- F
52	1		*AIR HOSE (WCP)	Not Necessary	45.00 F	*- F
53	1		*HORN - LOW PITCH (WCP)	Not Necessary	40.00 F	*- F
54	1		*ENGINE MOUNTING RH (WCP)	Not Necessary	140.00 F	*- F
55	1		*ENGINE MOUNTING BRACKET RH (WCP)	Not Necessary	65.00 F	*- F
56	1		*ENGINE LOWER COVER (WCP)	Not Necessary	190.00 F	*- F
57	1		*LOWER SILL PANEL RH (WCP)	Not Necessary	245.00 F	*- F

F=Franchise part.

Sub Total (\$\$)	7,645.00	5,480.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	764.50	548.00
Total Parts (\$\$)	8,409.50	6,028.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRT BUMPER, FRT GRILLE, INNER SHIELD & GARNISH - CLIPS (Necessary)	150.00	50.00
2	1	FRT NUMBER PLATE & FRAME (Missing)	35.00	35.00
Sub Total (\$\$)			185.00	85.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR BODY, PANEL BEAT & STRAIGHTEN/ALIGN - ACCIDENT AREA	New	1,200.00	800.00
2	SPRAY PAINT - FRT BUMPER, BONNET, FRT FENDER X2, FRT DOOR X2 & SUPPORT PANEL	New	1,200.00	1,000.00
3	ALIGN HEADLAMP/SENSOR & TEST WIRING	New	100.00	30.00
4	REFILL - RADIATOR COOLANT	New	80.00	50.00
5	REFILL - AIR COND GAS	New	80.00	80.00
Gross Labour Cost (\$\$)			2,660.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >