Adjuster Report 4/26/23, 10:54 AM

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG22009978/TNY3E2-1

WDD2050402R008880

26/04/2023 Date:

Chassis No:

REFERENCE

Reg. Date:

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1002267717 **Claimant Vehicle**

SLV4501L Insured Vehicle No: FBG6373Z No:

06/10/2022 Nature of Claim: TP Claim No: 287348 Date of Loss:

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLV4501L Reg No:

MERCEDES-BENZ C180, 1.6 AMG LINE (R18 Make & Model: **Engine No:** 27491030217756

23/01/2015 (Man. Year: 2014)

LED) (A)

Colour: Grev Odometer: 60780 km

Engine Capacity: 1595 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18 Front Left Side: Rear Left Side: Yokohama 6 mm Yokohama 6 mm Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

6,895.40 0.00	1,656.00	5,239.40	75.98
0.00			, 0.00
0.00	0.00	0.00	
2,820.00	1,165.00	1,655.00	58.69
0.00	0.00	0.00	
0.00	0.00	0.00	
9,715.40	2,821.00	6,894.40	70.96
	2,250.00		
9,715.40	2,250.00	7,465.40	76.84
	0.00 0.00 9,715.40	2,820.00 1,165.00 0.00 0.00 0.00 0.00 9,715.40 2,821.00 2,250.00	2,820.00 1,165.00 1,655.00 0.00 0.00 0.00 0.00 0.00 0.00 9,715.40 2,821.00 6,894.40 2,250.00

INSPECTION

Date of Assignment: 12/10/2022

Paul Hoe Enterprise Pte Ltd (HQ) Date Inspected: 12/10/2022 Inspected At: 1 KAKI BT AVE 6 #01-107

Singapore 417883

Estimated Period of Repair: 5.0 days

MOHD TAUFIKH BIN HAMID **HUEY YON** Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Apr 2023)

Parts: 143 MERCEDES-BENZ C180 1.6 AMG LINE (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLV4501L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH TAILLAMP ASSY	Face Scraped	1,080.00 FL	*780.00 FL
2	1		*RH REAR FENDER	Repair	2,030.00 FL	*- FL
3	1		*FUEL FILLER DOOR	Repair	125.00 FL	*- FL
4	1		*RH REAR DOOR	Repair	2,605.00 FL	*- FL
5	1		*RH REAR DOOR OUTER HANDLE	Not Necessary	256.00 FL	*- FL
6	1		*RH REAR RIM	Scraped / Grazed	1,060.00 FL	*1,060.00 FL
7	1		*RH REAR TYRE	Not Necessary	455.00 FS	*- FS
F=Fra	anchise	part. S=SpcNe	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	7,611.00	1,840.00
			- List Item Discount on L Items 10.00/10.00% (S\$)		715.60	184.00
				Total Parts (S\$)	6,895.40	1,656.00
				_		

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

4/26/23, 10:54 AM

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING	New	60.00	45.00
2	TO APPLY ANTI-RUST UNDERCOAT	New	120.00	30.00
3	LABOUR CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, T PANEL BEATING AFFECTED AND DAMAGED PARTS	O New	900.00	400.00
4	SPRAY PAINTING CHARGES TO PAINT THE REAR FENDER, FUEL FILLE DOOR, REAR DOOR, ETC	R New	1,200.00	600.00
5	TO CONDUCT 4-WHEEL COMPUTERISED ALIGNMENT TO REALIGN WHEELS	New	90.00	90.00
6	TO REMOVE AND REPLACE DAMAGED FRONT RIGHT HAND SUSPENSION PARTS (FOR CHECKING ONLY)	New	450.00	0.00
	Gross Labo	ur Cost (S\$)	2,820.00	1,165.00
	Report was unsubmitted during this p	orint-out.		

< END OF ESTIMATES >