



SINGAPORE POLICE FORCE



T/20230216/2034

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

3 of.

Report No. T/20230216/20

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't the certificate with you now, please fax a copy to 65474885 stating the report number as reference

Signature of Officer Recording The Report:
G /
SGT 2 MUHAMMAD FAIZ BIN
MUHAMMAD FAIZAL

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
16/02/2023 13:04

Officer In Charge Of Case:
TP / GIA /
SR STAFF SGT MUHAMMAD NOOR BIN
ABDUL RAHMAN
Contact No.: 65476219

Classification Of Case:

NP168

GUAN AUTO SERVICE

Blk 7 Sin Ming Industrial Estate Sector C, # #01-82 Singapore 575642

TO : Ong Beng Pheng

Blk 851 Hougang Central

#08-01 Singapore 530851

Date : 08 March 2023

Tax Invoice : GAS/SMS6116G/TP238789

Vehicle No : SMS 6116 G

Make/Model : Toyota Corolla Altis Elegance (Auto) (2WD)

Date Of Accident : 15.02.2023

PARTICULAR

Amount S\$

Front right side Portion damaged

Parts Replace, Repair, Straighten, Alignment,

Panel baeting, abour And spraypainting etc.

Cost Of Repair (Lump Sum Basis)

\$5,200.00

Singapore Dollars : Five Thousand Two Hundred Only

Total \$

\$5,200.00 Nett



Fong

GUAN AUTO SERVICE

Business Reg. No.: 107392/00C

Tel: 6451 1705 / 6455 2191 Fax: 6451 1706 H/P: 9618 7155
Email: keithvan@singnet.com.sg

Email: keithyap@singnet.com.sg

M/s Ong Beng Pheng

No: 5104

Tel : 90116263 H/P : —

Date: 3/3/2023

All Cheque should be crossed and made payable to
"Yap Motor Repair Service"

TOTAL \$S

For Yap Motor Repair Service



KTO Automobile Assessors

470 Segar Road #09-232 Singapore 670470 Email: ktoaa@singnet.com.sg HP: 98505311

Reg. No : 52941122M

INVOICE

M/S: Ong Beng Pheng
C/O Guan Auto Service
Blk 7 Sin Ming Industrial Estate Sector C,
#01-82 Singapore 575642.

Invoice No : 23-8789


Invoice Ref : TP/GAS/SMS6116G/8789

Date : 08 March 2023

| DESCRIPTION | AMOUNT |
|---|-----------|
| For Services Rendered Inspection report fees inclusive of : Transportation & Photographs Fifty-Two (52) copies Vehicle No : SMS 6116 G Make/Model : Toyota Corolla Altis Elegance (Auto) (2WD) | \$ 452.00 |
| Singapore Dollars: Four Hundred Fifty Two Only | \$ 452.00 |

Cheques should be made payable to KTO AUTOMOBILE ASSESSORS. Please indicate our Invoice No. on the reverse of your cheque.

KTO AUTOMOBILE ASSESSORS


Ong Ah Keng (CAE, AMIMI, MSAAA)
Automotive Appraiser

**ACCIDENT DAMAGED VEHICLE INSPECTION REPORT**

M/S : Ong Beng Pheng
C/O Guan Auto Service
Blk 7 Sin Ming Industrial Estate Sector C,
#01-82 Singapore 575642.

Date : 08 March 2023
Our Ref : TP/GAS/SMS6116G/8789

REFERENCE PARTICULARS

Date of Accident : 15 February 2023
Date of Inspection : 27 February 2023

Type of Inspection : Third Party Claim
Date of Re-Inspn : ~

VEHICLE PARTICULARS

Registration No : SMS 6116 G
Make : Toyota
Model : Corolla Altis Elegance (Auto) (2WD)
Year : 2020 (COE Expiry 07 Jan 2030)

Engine No : 1ZR0E97770
Chassis No : MR2BE3BE700005953
Odometer : 28185 km
Colour : Grey


CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Foot Brake : Serviceable
Hand Brake : Serviceable

General Body Work : Good
Steering : Serviceable
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

| | Make | Size | Thread Balance |
|-----------------|------------|-----------|----------------|
| Front Near side | : Michelin | 225/45R16 | 6 mm |
| Front Off Side | : Michelin | 225/45R16 | 6 mm |
| Rear Near Side | : Michelin | 225/45R16 | 6 mm |
| Rear off Side | : Michelin | 225/45R16 | 6 mm |

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the front off side portion
For details, refer to assessment for repairs and photographs
attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **\$5,200.00 nett** at lump sum basis. (Subject to GST if applicable)

Under normal circumstances, estimated period required for repairs : Five (5) working days.

Enclosed Fifty-Two (52) photographs depicting damage to the vehicle.

Inspection conducted at : Blk 7 #01-82 Sin Ming Industrial Estate Sector C, Singapore 575642.

Name of Workshop : Guan Auto Service.

In accordance to your instruction, we have **not authorise** repairs and inspection
was conducted strictly on a **"WITHOUT PREJUDICE BASIS"**.

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

| A) | SPARE PARTS | QTY PC/SET | ASSESSED CONDITION | ORIGINAL QUOTATION | REVISED QUOTATION |
|----|---|---------------|-----------------------|-------------------------------|----------------------|
| 1 | Front bumper | 1 | Grazed/Deformed | \$ 829.40 | \$ 581 ✓ 829.40 |
| 2 | Front bumper side support L/R @ \$45.30 | 2 | RH only (Damaged) | \$ 90.60 | \$ 45.30 ✓ |
| 3 | Front bumper reinforcement | 1 | Serviceable | \$ 460.50 | ~ X nn |
| 4 | Front bumper energy absorber | 1 | Torn | \$ 109.40 | \$ 109.40 ✓ |
| 5 | Front LED headlamp RH | 1 | Scratched/Hld Cracked | \$ 3,240.00 | \$ 3,240.00 ✓ |
| 6 | Front radiator grille | 1 | Hld Cracked | \$ 364.00 | \$ 328 ✓ 364.00 |
| 7 | Front radiator grille seal | 1 | Necessary | \$ 42.00 | \$ 42.00 ✓ |
| 8 | Front radiator grille lower | 1 | Grazed/Deformed | \$ 680.00 | \$ 387 ✓ 680.00 |
| 9 | Front windshield reservoir tank | 1 | Hld Kinked | \$ 230.90 | \$ 160.50 ✓ 230.90 |
| | | | | \$ 6,046.80 | \$ 5,541.00 |
| | | | Less 25% | \$ 4893.20 -25% 3669.90 | \$ 1,511.70 |
| | | | | \$ 4,535.10 | \$ 4,155.75 |
| B) | <u>S/NETT ITEM</u> | | | | |
| 10 | Front bumper clips | 1 set | Necessary | \$ 34.00 | \$ 34.00 30 |
| 11 | Front radiator grille top garnish clips | 1 set | Necessary | \$ 18.00 | \$ 18.00 15 |
| 12 | Front bumper fog lamp chrome trim RH | 1 set | Sheared off | \$ 468.00 | \$ 389 ✓ 468.00 |
| 13 | Front bumper fog lamp moulding RH | 1 | Torn | \$ 197.00 | \$ 197.00 ✓ |
| 14 | Front bumper fog lamp RH | 1 | Cracked | \$ 239.00 | \$ 239.00 ✓ |
| | Parts Total : | | | \$ 5,491.10 | \$ 870 5,111.75 |
| C) | <u>LABOUR CHARGES & MISC</u> | | | | |
| 15 | Spray painting on above new & repaired parts including supply of paint materials. spray 200+ coating \$250 | | | \$ 800.00 | \$ 650.00 450 |
| 16 | Remove damaged parts, knock out dent, straighten, panel beating, remove & reinstall necessary fittings to facilitate repairs, reshape, refit, adjust, replace and realign all relevant parts. | | | \$ 850.00 | \$ 700.00 250 |
| 17 | To cavity preservation on all affected areas. | | | \$ 60.00 | \$ 40.00 30 |
| 18 | Check wiring, lighting, electrical circuit, reconnection wire, socket focus headlights & central locking system for proper function. | | | \$ 50.00 | \$ 30.00 ✓ |
| | Labour Total : | | | \$ 1,760.00 | \$ 760 1,420.00 |
| | Total Parts and Labour | | | \$ 7,251.10 | \$ 6,531.75 |

FINAL LUMP SUM ADJUSTMENT 5299.90 \$ 5,200.00

L/S - 4239.92
= 4250

3 days

POINT OF IMPACT

The impact was confined to the front off side portion of the vehicle.
The damages appeared to be consistent as per the accident report statement.
Please refer the attached schedule and photographs for details.