

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23004077/UNP3M4**Date:** 05/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00096482201
Claimant Vehicle No :	SFX2215L	Insured Vehicle No :	GBG5500E
Date of Loss:	19/04/2023	Nature of Claim:	TP
		Claim No:	SNM23D202867/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFX2215L	Engine No:	27091031040193
Make & Model:	MERCEDES-BENZ B180, 1.6 STYLE (R16 LED) (A)	Chassis No:	WDD2462422J413797
Reg. Date:	09/01/2017 (Man. Year: 2016)	Odometer:	138579 km
Colour:	Silver		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,920.33	9,011.96	10,908.37	54.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,580.00	2,250.00	1,330.00	37.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,500.33	11,261.96	12,238.37	52.08
Approved Total (Overridden) (S\$)		9,000.00		
Nett Amount (S\$)	23,500.33	9,000.00	14,500.33	61.70

INSPECTION

Date of Assignment:	20/04/2023		
Date Inspected:	20/04/2023	Inspected At:	AUTOBAY PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-11 SINGAPORE 417883
Estimated Period of Repair:	6.0 days		

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 May 2023)
Parts:	144	MERCEDES-BENZ B180 1.6 STYLE (R16 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFX2215L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BONNET	Repair	1,858.00 FN	*- FN
2	2	*FRONT BONNET LOCKS -LH/RH	Not Necessary	323.00 FN	*- FN
3	2	*FRONT BONNET LOCK BRACKETS -LH/RH	Not Necessary	391.20 FN	*- FN
4	2	*FRONT BONNET LOCK STRIKERS	Not Necessary	110.40 FN	*- FN
5	2	*FRONT BONNET STOPPERS	Not Necessary	117.70 FN	*- FN
6	1	*FRONT BONNET SAFETY LOCK	Not Necessary	141.25 FN	*- FN
7	1	*FRONT BONNET SEAL	Not Necessary	42.20 FN	*- FN
8	1	*FRONT BONNET INSULATOR	Not Necessary	141.95 FN	*- FN
9	15	*FRONT BONNET INSULATOR CLIPS	Not Necessary	82.50 FN	*- FN
10	2	*FRONT BONNET ACTUATORS -LH/RH	Not Necessary	599.08 FN	*- FN
11	2	*FRONT BONNET DAMPERS -LH/RH	Not Necessary	489.00 FN	*- FN
12	1	*FRONT BUMPER	Distorted	1,680.00 FN	*1,285.00 FN
13	1	*FRONT BUMPER CENTRE GRILLE	Not Necessary	89.95 FN	*- FN
14	1	*FRONT BUMPER LOWER SPOILER	Not Necessary	280.93 FN	*- FN
15	1	*FRONT BUMPER LOWER MOULDING -CENTRE	Necessary	261.95 FN	*261.95 FN
16	2	*FRONT BUMPER LOWER MOULDINGS -LH/RH	Necessary	363.30 FN	*363.30 FN
17	1	*FRONT BUMPER SIDE GRILLES	N/S Twisted /O/S Not Necessary	220.50 FN	*110.25 FN
18	1	*FRONT BUMPER PDC SENSORS -LH	N/S Malfunction	580.00 FN	*205.00 FN
19	1	*FRONT BUMPER PDC SENSORS -LOWER LH	Not Necessary	290.00 FN	*- FN
20	1	*FRONT BUMPER TOP SEAL	Necessary	86.90 FN	*86.90 FN
21	1	*FRONT BUMPER TOP GUIDE	Cracked	220.50 FN	*220.50 FN
22	1	*FRONT BUMPER SPONGE	Torn	125.00 FN	*125.00 FN
23	1	*FRONT BUMPER FRAME PAD -CENTRE	Not Necessary	241.50 FN	*- FN
24	1	*FRONT BUMPER SIDE PADS LH	No such part	95.00 FN	*- FN
25	1	*FRONT BUMPER REINFORCEMENT	Repair	780.00 FN	*- FN
26	2	*FRONT BUMPER REINFORCEMENT STAYS	Not Necessary	371.80 FN	*- FN
27	2	*FRONT BUMPER SIDE GRIDS LH/RH	Not Necessary	137.10 FN	*- FN
28	1	*FRONT FENDER LH	Distorted	765.00 FN	*765.00 FN
29	15	*FRONT FENDER INNER SHIELD CLIPS	Necessary	82.50 FN	*82.50 FN
30	1	*FRONT FENDER INNER SHIELD	Torn	185.00 FN	*185.00 FN
31	1	*FRONT FENDER BRACKET	Bent	110.50 FN	*110.50 FN
32	1	*FRONT HEADLAMP LH	Cracked	3,280.00 FN	*2,820.11 FN
33	1	*FRONT HEADLAMP CONTROL UNITS LH	Not Necessary	850.00 FN	*- FN
34	1	*FRONT HEADLAMP LOWER BRACKETS LH	Cracked	86.50 FN	*86.50 FN
35	1	*FRONT HEADLAMP MOULDINGS LH	Not fitted	211.53 FN	*- FN
36	1	*FRONT FOG LAMP COVER LH	Repeated	86.00 FN	*- FN
37	1	*FRONT FOG LAMP CHROME LH	Scratched	98.00 FN	*98.00 FN
38	1	*FRONT SUPPORT PANEL	Cracked	381.70 FN	*381.70 FN
39	1	*FRONT SUPPORT TOP GARNISH	Not Necessary	185.70 FN	*- FN
40	1	*FRONT SHOCK ABSORBER LH TOP MOULDING	Twisted	85.00 FN	*85.00 FN
41	1	*FRONT SHOCK ABSORBER LH	Bent	820.00 FN	*645.20 FN
42	1	*FRONT KNUCKLE ARM LH	Bent	1,075.00 FN	*945.10 FN
43	1	*FRONT KNUCKLE BEARING LH	Necessary	88.00 FN	*88.00 FN
44	1	*FRONT LOWER ARM LH	Bent	640.00 FN	*485.00 FN
45	1	*ANTI-ROLL BAR ENDLINK LH	Not Necessary	165.00 FN	*- FN
46	1	*FRONT TYRE LH 205/55R16	Serviceable	280.00 FS	*- FS

Report was unsubmitted during this print-out.

5/5/23, 12:48 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT WHEEL RIM LH	Warped	1,290.00 FS	*520.00 FS
F=Franchise part. S=SpcNett. N=NettItemDisc.						
					Sub Total (\$)	20,886.14
					- Nett Item Discount on N Items 5.00/10.00% (\$)	965.81
					Total Parts (\$)	19,920.33
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGE	New	150.00	100.00
2	TO CHECK ELECTRICAL WIRING SYSTEMS	New	100.00	20.00
3	TO CONDUCT COMPUTERIZED 4 - WHEEL ALIGNMENT	New	180.00	60.00
4	TO REMOVE FRONT LH SHOCK ABSORBER ,KNUCKLE ARM ,BEARING ,ENDLINK ,ETC	New	450.00	150.00
5	TO DIAGNOSE ,ERASE FAULT MEMORY AFTER REPAIR	New	150.00	80.00
6	TO RESPRAY UNDERCOATING	New	150.00	40.00
7	TO RESPRAY PAINTING & ETC	New	1,200.00	800.00
8	PANEL BEATING ,CUT ,WELD REMOVE AND REPLACING ABOVE PARTS	New	1,200.00	1,000.00
Gross Labour Cost (\$\$)			3,580.00	2,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >