

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS/AIS23001908/DQP3E2-1
Date: 29/05/2023**REFERENCE**

Insured/Claimant:	GIS MOTORING PTE. LTD.	Policy No:	SP20031111275
Date of Loss:	13/02/2023	Nature of Claim:	OD
		Claim No:	202332005461

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME2476S		
Make & Model:	RENAULT GRAND SCENIC IV, 1.5 DCI EU6 (A)	Engine No:	K9KF649D021403
Reg. Date:	26/12/2017 (Man. Year: 2017)	Chassis No:	VF1RFA00059238203
Colour:	Red	Odometer:	0 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	S\$78,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R20	Rear Tyre Size:	195/55 R20
Front Left Side:	Grenlander 5 mm	Rear Left Side:	Grenlander 5 mm
Front Right Side:	Grenlander 5 mm	Rear Right Side:	Grenlander 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,346.00	27,608.00	6,738.00	19.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,770.00	3,030.00	4,740.00	61.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	42,116.00	30,638.00	11,478.00	27.25
Approved Total (Overridden) (S\$)		26,000.00		
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
Nett Amount (S\$)	40,616.00	24,500.00	16,116.00	39.68

INSPECTION

Date of Assignment:	20/04/2023	SV Autoworks Pte Ltd (HQ)
Date Inspected:	21/02/2023 Inspected At:	8 Kaki Bukit Avenue 4, #02-24 Premier @ Kaki Bukit
Estimated Period of Repair:	14.0 days	Singapore 415875

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 May 2023)
Parts:	M1-MPV	RENAULT GRAND SCENIC IV 1.5 DCI EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME2476S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Buckled	1,150.00 FL	*1,150.00 FL
2	1		*FRONT BONNET RH HINGE	Bent	110.00 FL	*110.00 FL
3	1		*FRONT BONNET LH HINGE	Bent	110.00 FL	*110.00 FL
4	1		*FRONT BONNET RH RUBBER	Serviceable	60.00 FL	*- FL
5	1		*FRONT BONNET LH RUBBER	Serviceable	60.00 FL	*- FL
6	1		*FRONT BONNET INSULATOR	Crumpled	150.00 FL	*150.00 FL
7	1		*FRONT BONNET LOCK	Bent	200.00 FL	*200.00 FL
8	1		*FRONT GRILLE BASE	Broken	400.00 FL	*400.00 FL
9	1		*FRONT GRILLE OUTER CHROME GARNISH	Cracked	290.00 FL	*290.00 FL
10	1		*FRONT GRILLE MOULDING	Bent	190.00 FL	*190.00 FL
11	1		*FRONT GRILLE LOWER CHROME MOULDING	Cracked	270.00 FL	*270.00 FL
12	1		*FRONT GRILLE EMBLEM	Broken	190.00 FL	*190.00 FL
13	1		*FRONT RH HEADLAMP	Broken	770.00 FL	*770.00 FL
14	1		*FRONT LH HEADLAMP	Mtg Cracked	770.00 FL	*770.00 FL
15	1		*FRONT RH HEADLAMP BRACKET	Bent	50.00 FL	*50.00 FL
16	1		*FRONT LH HEADLAMP BRACKET	Not Necessary	50.00 FL	*- FL
17	1		*FRONT BUMPER	Torn	1,450.00 FL	*1,450.00 FL
18	1		*FRONT BUMPER LOWER PAD	Distorted	400.00 FL	*400.00 FL
19	1		*FRONT BUMPER CENTRE LOWER GRILLE	Deformed	390.00 FL	*390.00 FL
20	1		*FRONT BUMPER TOWING COVER	Cut	30.00 FL	*30.00 FL
21	1		*FRONT BUMPER RH FOG LAMP	Dislodged	170.00 FL	*170.00 FL
22	1		*FRONT BUMPER LH FOG LAMP	Not Necessary	170.00 FL	*- FL
23	1		*FRONT BUMPER RH FOG LAMP COVER	Dislodged	170.00 FL	*170.00 FL
24	1		*FRONT BUMPER LH FOG LAMP COVER	Not Necessary	170.00 FL	*- FL
25	1		*FRONT BUMPER RH SIDE RETAINER	Dislodged	110.00 FL	*110.00 FL
26	1		*FRONT BUMPER LH SIDE RETAINER	Not Necessary	110.00 FL	*- FL
27	1		*FRONT BUMPER RH INNER PAD	Broken	90.00 FL	*90.00 FL
28	1		*FRONT BUMPER LH INNER PAD	Not Necessary	90.00 FL	*- FL
29	1		*FRONT BUMPER SPONGE	Broken	80.00 FL	*80.00 FL
30	1		*FRONT BUMPER REINFORCEMENT	Bent	630.00 FL	*630.00 FL
31	1		*FRONT BUMPER REINFORCEMENT RH BRACKET	Bent	140.00 FL	*140.00 FL
32	1		*FRONT BUMPER REINFORCEMENT LH BRACKET	Bent	140.00 FL	*140.00 FL
33	1		*FRONT BUMPER UNDER COVER	Cracked	450.00 FL	*450.00 FL
34	10		*FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
35	1		*FRONT SUPPORT PANEL	Broken	1,050.00 FL	*1,050.00 FL
36	1		*FRONT SUPPORT PANEL TOP COVER	Broken	130.00 FL	*130.00 FL
37	10		*FRONT SUPPORT PANEL TOP COVER CLIPS	Necessary	30.00 FL	*30.00 FL
38	1		*AIRCON CONDENSER	Bent	880.00 FL	*880.00 FL
39	1		*AIRCON CONDENSER DISCHARGE PIPE	Bent	350.00 FL	*350.00 FL
40	1		*AIRCON CONDENSER RECEIVER PIPE	Bent	280.00 FL	*280.00 FL
41	1		*AIRCON CONDENSER SUCTION PIPE	Bent	380.00 FL	*380.00 FL
42	1		*RADIATOR	Bent	690.00 FL	*690.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*RADIATOR TOP HOSE	Deformed	60.00 FL	*60.00 FL
44	1		*RADIATOR LOWER HOSE	Not Necessary	60.00 FL	*- FL
45	1		*RADIATOR FAN MOTOR	Broken	870.00 FL	*870.00 FL
46	1		*TURBO COOLER	Dented	780.00 FL	*780.00 FL
47	1		*TURBO COOLER DUCT	Broken	150.00 FL	*150.00 FL
48	1		*AIR CLEANER BOX	Broken	210.00 FL	*210.00 FL
49	1		*AIR CLEANER BOX HOSE	Deformed	50.00 FL	*50.00 FL
50	1		*ALTERNATOR	Not Necessary	800.00 FL	*- FL
51	1		*AIRCON COMPRESSOR	Broken	2,000.00 FL	*2,000.00 FL
52	1		*FAN BELT	Torn	60.00 FL	*60.00 FL
53	1		*WIPER TANK	Not Necessary	160.00 FL	*- FL
54	1		*FRONT RH FENDER	Broken	550.00 FL	*550.00 FL
55	1		*FRONT RH FENDER INNER SHIELD	Torn	310.00 FL	*310.00 FL
56	10		*FRONT RH FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FL	*- FL
57	1		*FRONT LH FENDER	Repair	550.00 FL	*- FL
58	1		*DASHBOARD	Broken	3,100.00 FL	*3,100.00 FL
59	1		*DASHBOARD COVER	No such part	800.00 FL	*- FL
60	1		*STEERING AIRBAG	Activated	950.00 FL	*950.00 FL
61	1		*PASSENGER AIRBAG	Activated	1,000.00 FL	*1,000.00 FL
62	1		*STEERING CLOCK SPRING SENSOR	Activated	600.00 FL	*600.00 FL
63	1		*AIRBAG SENSOR	Activated	220.00 FL	*220.00 FL
64	1		*AIRBAG ECU	Activated	1,200.00 FL	*1,200.00 FL
65	1		*FRONT RH SEAT BELT	Activated	630.00 FL	*630.00 FL
66	1		*FRONT LH SEAT BELT	Activated	630.00 FL	*630.00 FL
67	1		*REAR RH SEAT BELT	Activated	730.00 FL	*730.00 FL
68	1		*REAR LH SEAT BELT	Activated	730.00 FL	*730.00 FL
69	1		*FRONT NO. PLATE	Cut	40.00 FL	*40.00 FL
70	1		*FRONT WINDSCREEN	Not Necessary	250.00 FS	*- FS
71	1		*FRONT SUPPORT PANEL AIR DUCT - INNER	Broken	270.00 FL	*270.00 FL
72	1		*FRONT SUPPORT PANEL AIR DUCT - OUTER	Broken	620.00 FL	*620.00 FL
73	1		*FRONT SUPPORT PANEL TOP RH BRACKET	Bent	360.00 FL	*360.00 FL
74	1		*FRONT SUPPORT PANEL TOP LH BRACKET	Bent	350.00 FL	*350.00 FL
75	1		*FRONT SUPPORT PANEL LOWER RH BRACKET	Bent	130.00 FL	*130.00 FL
76	1		*FRONT SUPPORT PANEL LOWER LH BRACKET	Bent	130.00 FL	*130.00 FL
77	1		*RADIATOR AIR DEFLECTOR AIR DUCT	Broken	160.00 FL	*160.00 FL
78	1		*RH HORN	Broken	260.00 FL	*260.00 FL
79	1		*ENGINE ECU COVER	Broken	170.00 FL	*170.00 FL
80	1		*THROTTLE BODY AIR HOSE	Torn	550.00 FL	*550.00 FL
81	1		*AIR CLEANER BOX AIR HOSE DUCT	Broken	950.00 FL	*950.00 FL
82	1		*RH FENDER BRACKET	Bent	190.00 FL	*190.00 FL
83	1		*BONNET LOCK CABLE	Broken	260.00 FL	*260.00 FL
84	1		*BONNET LOCK RELEASE HANDLE	Broken	90.00 FL	*90.00 FL
85	1		*ENGINE OIL DIPSTICK	Broken	240.00 FL	*240.00 FL
86	1		*RH WIPER GRILLE SIDE COVER	Cut	240.00 FL	*240.00 FL
87	1		*PARKING SENSOR	Damaged	750.00 FL	*750.00 FL
88	1		*PARKING SENSOR WIRE HARNESS	Torn	270.00 FL	*270.00 FL
89	1		*AIRCON TEMPERATURE SENSOR	Dislodged	170.00 FL	*170.00 FL
90	1		*BONNET COVER - BLACK	Bent	760.00 FL	*760.00 FL
91	1		*FRONT RH CHASSIS	Repair	2,500.00 FL	*- FL
92	1		*FRONT LH CHASSIS	Repair	2,500.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	42,870.00	34,510.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	8,524.00	6,902.00
Total Parts (\$\$)	34,346.00	27,608.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REPAIR FRONT PANEL, FRONT GRILL, FRONT CENTER PANEL, FRONT SUPPORT PANEL, AND OTHER PARTS	New	4,000.00	1,200.00
2	R&R RADIATOR	New	150.00	50.00
3	R&R CONDENSER	New	150.00	120.00
4	R&R INTERCOOLER	New	150.00	50.00
5	R&R DASHBOARD	New	300.00	200.00
6	R&R AIRBAGS	New	400.00	200.00
7	AIRBAGS RESETTING AND SENSOR CODING	New	500.00	350.00
8	REFOCUS HEAD LIGHTS	New	120.00	30.00
9	CHECK WIRING	New	200.00	30.00
10	SPRAY AFFECTED AREA	New	1,800.00	800.00
Gross Labour Cost (\$\$)			7,770.00	3,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >