

A.S. REC. BY:

REF:

08/AUS 23001908/D 273-1

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: 1500

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bel. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 14 days Res.: Yes or No

Turn Sum: 3/P % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SME 2476S Yr Regn: Dec, 2007

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Grand Scenic C.C 1461

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: N/A T/Radio: Insured / Std / NI / NA

Eng/No: K9KF649D021403

C/No: VF1RFA00059238203

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55 R20

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Greenlander

Front Rear

R/Bal: 5 mm R/Bal: 5 mm

L/Bal: 5 mm L/Bal: 5 mm

D.O.A. 13/02/2023 D.O.I. 21/02/2023

Survey held at Vin's Motor Sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rnt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Allianz OD

20/04/22 AIS informed vehicle tow to SV works for repair.

MV 78K

29/05/23 LS \$26000 as agreed between AIS &amp; SV works.

LTA 29.1K

(Red \$14404, 36%)

LTA 48.9K

15/03/23 Resurvey and found 2 front chassis bent. Recommended to be total loss as structure affected.

15/3/23 Submit total loss report due to structure damage.

Date/Time, File Pass to?

29/05/23 : Prel. Report

15/5/23 : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 14

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Add Fee:



Site Insp (\$



Interview (\$



Tech. Inve (\$

Report Format:

MER-OP/7-6

I certify that the above information is true and correct.

26000



# Vin's

**Vin's Motor Pte Ltd**  
160 Sin Ming Drive  
#03-03 Sin Ming Autocity  
Singapore 575722  
Tel : 6453 2121 Fax : 6459 9795  
GST Registration No. 199906067G

## Estimated Cost of Repair

<b>Attention To</b>	<b>Allianz Insurance Singapore Pte Ltd</b>	<b>Claim Details</b>
	79 Robinson Road	<b>Case Ref. No.</b> : OD/022023/5984
	#09-01	<b>Date</b> : 13-02-2023
	Singapore 068897	<b>Accident Date</b> : 13-02-2023

### Vehicle Details

**Make & Model** : Renault GRAND SCENIC IV 1.5  
DCI AT EU6

**Chassis No** : VF1RFA00059238203

**Registration No** : SME2476S

S/N	Description	Qty	Amount (\$\$)	
1	FRONT BONNET <i>brn</i>	1.00	\$1,150.00	✓
2	FRONT BONNET RH HINGE <i>brn</i>	1.00	\$110.00	✓
3	FRONT BONNET LH HINGE <i>brn</i>	1.00	\$110.00	✓
4	FRONT BONNET RH RUBBER <i>brn</i>	1.00	\$60.00	X
5	FRONT BONNET LH RUBBER <i>brn</i>	1.00	\$60.00	X
6	FRONT BONNET INSULATOR <i>crushed</i>	1.00	\$150.00	✓
7	FRONT BONNET LOCK <i>brn</i>	1.00	\$200.00	✓
8	FRONT GRILLE BASE <i>broken</i>	1.00	\$400.00	✓
9	FRONT GRILLE OUTER CHROME GARNISH <i>crack</i>	1.00	\$290.00	✓
10	FRONT GRILLE MOULDING <i>brn</i>	1.00	\$190.00	✓
11	FRONT GRILLE LOWER CHROME MOULDING <i>crack</i>	1.00	\$270.00	✓
12	FRONT GRILLE EMBLEM <i>broken</i>	1.00	\$190.00	✓
13	FRONT RH HEADLAMP <i>broken</i>	1.00	\$770.00	✓
14	FRONT LH HEADLAMP <i>minorly crack</i>	1.00	\$770.00	✓
15	FRONT RH HEADLAMP BRACKET <i>brn</i>	1.00	\$50.00	✓
16	FRONT LH HEADLAMP BRACKET <i>brn</i>	1.00	\$50.00	X
17	FRONT BUMPER <i>brn</i>	1.00	\$1,450.00	✓
18	FRONT BUMPER LOWER PAD <i>distorted</i>	1.00	\$400.00	✓
19	FRONT BUMPER CENTRE LOWER GRILLE <i>displaced</i>	1.00	\$390.00	✓
20	FRONT BUMPER TOWING COVER <i>crack</i>	1.00	\$30.00	✓
21	FRONT BUMPER RH FOG LAMP <i>dislodged</i>	1.00	\$170.00	✓
22	FRONT BUMPER LH FOG LAMP <i>brn</i>	1.00	\$170.00	X
23	FRONT BUMPER RH FOG LAMP COVER <i>dislodged</i>	1.00	\$170.00	✓
24	FRONT BUMPER LH FOG LAMP COVER <i>brn</i>	1.00	\$170.00	X
25	FRONT BUMPER RH SIDE RETAINER <i>dislodged</i>	1.00	\$110.00	✓
26	FRONT BUMPER LH SIDE RETAINER <i>brn</i>	1.00	\$110.00	X
27	FRONT BUMPER RH INNER PAD <i>broken</i>	1.00	\$90.00	✓
28	FRONT BUMPER LH INNER PAD <i>brn</i>	1.00	\$90.00	X
29	FRONT BUMPER SPONGE <i>broken</i>	1.00	\$80.00	✓
30	FRONT BUMPER REINFORCEMENT <i>brn</i>	1.00	\$630.00	✓

# Vin's

**Vin's Motor Pte Ltd**  
160 Sin Ming Drive  
#03-03 Sin Ming Autocity  
Singapore 575722  
Tel : 6453 2121 Fax : 6459 9795  
GST Registration No. 199906067G

31	FRONT BUMPER REINFORCEMENT RH BRACKET <i>yt</i>	1.00	\$140.00	✓
32	FRONT BUMPER REINFORCEMENT LH BRACKET <i>yt</i>	1.00	\$140.00	2✓
33	FRONT BUMPER UNDER COVER <i>crack</i>	1.00	\$450.00	2✓
34	FRONT BUMPER CLIPS <i>huc</i>	10.00	\$30.00	✓
35	FRONT SUPPORT PANEL <i>broken</i>	1.00	\$1,050.00	✓
36	FRONT SUPPORT PANEL TOP COVER <i>broken</i>	1.00	\$130.00	✓
37	FRONT SUPPORT PANEL TOP COVER CLIPS <i>huc</i>	10.00	\$30.00	✓
38	AIRCON CONDENSER <i>yt</i>	1.00	\$880.00	✓
39	AIRCON CONDENSER DISCHARGE PIPE <i>yt</i>	1.00	\$350.00	2✓
40	AIRCON CONDENSER RECEIVER PIPE <i>yt</i>	1.00	\$280.00	2✓
41	AIRCON CONDENSER SUCTION PIPE <i>yt</i>	1.00	\$380.00	2✓
42	RADIATOR <i>yt</i>	1.00	\$690.00	✓
43	RADIATOR TOP HOSE <i>deformed</i>	1.00	\$60.00	2✓
44	RADIATOR LOWER HOSE <i>huc</i>	1.00	\$60.00	X
45	RADIATOR FAN MOTOR <i>broken</i>	1.00	\$870.00	2✓
46	TURBO COOLER <i>Deformed</i>	1.00	\$780.00	2✓
47	TURBO COOLER DUCT <i>broken</i>	1.00	\$150.00	✓
48	AIR CLEANER BOX <i>broken</i>	1.00	\$210.00	2✓
49	AIR CLEANER BOX HOSE <i>deformed</i>	1.00	\$50.00	2✓
50	ALTERNATOR ?	1.00	\$800.00	?
51	AIRCON COMPRESSOR ?	1.00	\$2,000.00	?
52	FAN BELT ?	1.00	\$60.00	?
53	WIPER TANK <i>huc</i>	1.00	\$160.00	X
54	FRONT RH FENDER <i>broken</i>	1.00	\$550.00	✓
55	FRONT RH FENDER INNER SHIELD <i>turn</i>	1.00	\$310.00	2✓
56	FRONT RH FENDER INNER SHIELD CLIPS <i>huc</i>	10.00	\$30.00	X
57	FRONT LH FENDER <i>huc</i>	1.00	\$550.00	X
58	DASHBOARD <i>broken</i>	1.00	\$3,100.00	✓
59	DASHBOARD COVER <i>huc</i>	1.00	\$800.00	X
60	STEERING AIRBAG <i>activated</i>	1.00	\$950.00	✓
61	PASSENGER AIRBAG <i>activated</i>	1.00	\$1,000.00	✓
62	STEERING CLOCK SPRING SENSOR <i>activated</i>	1.00	\$600.00	✓
63	AIRBAG SENSOR <i>activated</i>	1.00	\$220.00	✓
64	AIRBAG ECU <i>activated</i>	1.00	\$1,200.00	✓
65	FRONT RH SEAT BELT <i>activated</i>	1.00	\$630.00	✓
66	FRONT LH SEAT BELT <i>activated</i>	1.00	\$630.00	✓
67	REAR RH SEAT BELT <i>activated</i>	1.00	\$730.00	✓
68	REAR LH SEAT BELT <i>activated</i>	1.00	\$730.00	✓
			\$30,660.00	
			\$3,066.00	
			\$33,726.00	
69	FRONT NO. PLATE <i>cut / scratched</i>	1.00	\$40.00	

Margin: 10%

# Vin's

**Vin's Motor Pte Ltd**  
 160 Sin Ming Drive  
 #03-03 Sin Ming Autocity  
 Singapore 575722  
 Tel : 6453 2121 Fax : 6459 9795  
 GST Registration No. 199906067G

70	COOLANT 44	1.00	\$80.00 44
71	TO REFILL AIRCON GAS	1.00	<del>\$150.00</del> 120/-
72	TO RESET HEADLAMP SYSTEM AND ECU	1.00	<del>\$280.00</del> 7150/-
73	TO RESET AIRBAG SYSTEM AND ECU	1.00	\$380.00 350/-
74	TO REMOVE AND REPLACE DASHBOARD	1.00	<del>\$380.00</del> 180/- 250/-
75	TO REPAIR FRONT DAMAGES	1.00	<del>\$980.00</del> 900/-
76	TO SPRAY PAINTING	1.00	<del>\$1,200.00</del> 800/-
Subtotal w/o GST:			\$37,216.00

21/02/2023 @ 1630h

Mr Andrew

P/Pant.

*[Signature]*

LKK club

*[Signature]*

Excurs ISA.

- Photos after  
 repair with  
 damaged parts.

- No spare parts.  
 Need to indent.

**LKK Auto Consultants** hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Issued by Iswan

This is a computer-generated document. No signature is required.



## Estimated Cost of Repair (Supplementary)

Attention To : Allianz Insurance Singapore Pte Ltd  
79 Robinson Road  
#09-01  
Singapore 068897

### Claim Details

Case Ref. No. : OD/022023/5984  
Date : 13-02-2023  
Accident Date : 13-02-2023

### Vehicle Details

Make & Model : Renault GRAND SCENIC IV 1.5  
DCI AT EU6  
Chassis No : VF1RFA00059238203  
Registration No : SME2476S

S/N	Description	Qty	Amount (\$\$)	
1	FRONT SUPPORT PANEL AIR DUCT - INNER <i>broken</i>	1.00	\$270.00	✓
2	FRONT SUPPORT PANEL AIR DUCT - OUTER <i>broken</i>	1.00	\$620.00	✓
3	FRONT SUPPORT PANEL TOP RH BRACKET <i>bt</i>	1.00	\$360.00	✓
4	FRONT SUPPORT PANEL TOP LH BRACKET <i>bt</i>	1.00	\$350.00	✓
5	FRONT SUPPORT PANEL LOWER RH BRACKET <i>bt</i>	1.00	\$130.00	✓
6	FRONT SUPPORT PANEL LOWER LH BRACKET <i>bt</i>	1.00	\$130.00	✓
7	RADIATOR AIR DEFLECTOR AIR DUCT <i>broken</i>	1.00	\$160.00	✓
8	RH HORN <i>broken</i>	1.00	\$260.00	✓
9	ENGINE ECU COVER <i>broken</i>	1.00	\$170.00	✓
10	THROTTLE BODY AIR HOSE <i>torn</i>	1.00	\$550.00	✓
11	AIR CLEANER BOX AIR HOSE DUCT <i>broken</i>	1.00	\$950.00	✓
12	RH FENDER BRACKET <i>bt</i>	1.00	\$190.00	✓
13	BONNET LOCK CABLE <i>broken</i>	1.00	\$260.00	✓
14	BONNET LOCK RELEASE HANDLE <i>broken</i>	1.00	\$90.00	✓
15	ENGINE OIL DIPSTICK <i>broken</i>	1.00	\$240.00	✓
16	RH WIPER GRILLE SIDE COVER <i>cut</i>	1.00	\$240.00	✓
17	PARKING SENSOR <i>Dem</i>	1.00	\$750.00	✓
18	PARKING SENSOR WIRE HARNESS <i>torn</i>	1.00	\$270.00	✓
19	AIRCON TEMPERATURE SENSOR <i>dislodged</i>	1.00	\$170.00	✓
20	BONNET COVER -BLACK <i>bt</i>	1.00	\$760.00	✓
21	FRONT RH CHASSIS <i>Demol</i>	1.00	\$2,500.00	✓
22	FRONT LH CHASSIS <i>bt</i>	1.00	\$2,500.00	✓

\$11,920.00

Margin: 10%

\$1,192.00

\$13,112.00

Vin's


Vin's Motor Pte Ltd  
160 Sin Ming Drive  
#03-03 Sin Ming Autocity  
Singapore 575722  
Tel : 6453 2121 Fax : 6459 9795  
GST Registration No. 199906067G

Subtotal w/o GST:


\$13,112.00

08/03/2023 @ 1000h

Hot Air



LKK Auto



2 front chassis  
adjust.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Issued by Raymond Teo

This is a computer-generated document. No signature is required.