

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJF 9145G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET	NOT NECESSARY	701.40	-
2	FRONT HEADLAMPS	NOT NECESSARY	991.36	-
1	FRONT GRILLE	NOT NECESSARY	255.90	-
1	FRONT GRILLE LOGO	NOT NECESSARY	67.52	-
1	FRONT GRILLE CHROME MOULDING	NOT NECESSARY	144.58	-
1	FRONT BUMPER	DENTED / TORN	486.30	486.30
2	FRONT BUMPER BRACKETS	NOT NECESSARY	619.70	-
2	FRONT BUMPER FOG LAMP COVERS	NOT NECESSARY	164.64	-
1	FRONT BUMPER LOWER GRILLE	CUT	98.90	98.90
1	FRONT BUMPER REINFORCEMENT	DENTED	422.45	312.20
2	FRONT BUMPER REINFORCEMENT STAY	NOT NECESSARY	331.00	-
2	FRONT BUMPER SIDE RETAINERS	NECESSARY	114.40	114.40
1	FRONT BUMPER TOW HOOK COVER	NOT NECESSARY	36.40	-
1	FRONT BUMPER LOGO	NOT NECESSARY	66.20	-
1	FRONT BUMPER INNER TOP BEAM	NOT NECESSARY	169.70	-
1	FRONT BUMPER TOP SUPPORT GARNISH	NOT NECESSARY	169.70	-
	LESS 25% DISCOUNT		-1,210.04	-252.95
			3,630.11	758.85
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	60.00	40.00
1	FRONT NUMBER PLATE WITH HOLDER (SN)	CRACKED	50.00	40.00
			110.00	80.00
	<u>LABOUR</u>			
	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING.		80.00	20.00
	TO APPLY UNDERCOATING.	NOT NECESSARY	80.00	-
	PANEL BEATING.		1,200.00	380.00
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS.		1,000.00	400.00
			2,360.00	800.00
	GRAND TOTAL		6,100.11	1,638.85

Report Ref No. CS/LIP23004079/Uqy3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,300.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/LIP23004079/Uqy3e2

MARKET VALUE: \$2,500.00 (EST)-LTA REIMBURSEMENT VALUE: \$570.00=NETT VALUE: \$1,930.00

CHUA KANG SENG

**Licensed Appraiser**