

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS23004080/WWY3Q2**Date:** 07/06/2023REFERENCE

Handling Insurer: ECICS Limited Policy No:

**Claimant Vehicle No :** GBC7984A **Insured Vehicle No :** SKQ3374G

Date of Loss: 04/04/2023 Nature of Claim: TP Claim No: DMPC2300243H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBC7984A**

Make & Model: ADIVA AD1 200, 190cc 3W Engine No: 1KD2321483

Reg. Date: 30/10/2013 (Man. Year: 2013) Chassis No: JTFHT02P100122121

Colour: Silver Odometer: 212693 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15

Front Left Side: Longway 6 mm Rear Left Side: Longway 6 mm

Front Right Side: Longway 6 mm Rear Right Side: Longway 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,858.56	2,145.05	713.51	24.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	1,040.00	1,110.00	51.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,008.56</b>	<b>3,185.05</b>	<b>1,823.51</b>	<b>36.41</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,550.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,008.56</b>	<b>2,550.00</b>	<b>2,458.56</b>	<b>49.09</b>

INSPECTION

Date of Assignment: 20/04/2023

Date Inspected: 20/04/2023 Inspected At: AUTO INSURE PTE LTD (HQ)  
6 MARSILING LANE  
Singapore 739145

Estimated Period of Repair: 4.0 days

**Adjuster:** Mohdakid**Manager:** XinYu

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 07 Jun 2023)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC7984A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,950.00 FL	*1,917.00 FL
2	1		*TAILGATE LOCK	Jammed	280.90 FL	*280.90 FL
3	1		*TAILGATE LOGO	Necessary	180.00 FL	*66.70 FL
4	1		*TAILGATE EMBLEM (TOYOTA)	Necessary	65.80 FL	*65.80 FL
5	1		*TAILGATE EMBLEM (HIACE)	Necessary	65.80 FL	*65.80 FL
6	1		*REAR BUMPER	Scratched / Dented	425.90 FL	*397.20 FL
7	1		*REAR BUMPER BRACKET LH	Serviceable	89.90 FL	*- FL
8	1		*REAR BUMPER BRACKET RH	Serviceable	89.90 FL	*- FL
9	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
10	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
11	1		*TAILGATE STICKER (70KM/H)	Necessary	120.00 FS	*20.00 FS
12	1		*SUNDRIES (SAND PAPER,WELDING WIRE ETC)	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,488.20	2,843.40
- List Item Discount on L Items 20.00/25.00% (S\$)	629.64	698.35
Total Parts (S\$)	2,858.56	2,145.05

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	New	1,000.00	400.00
2	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	New	100.00	30.00
3	TO REMOVE & REFIT REAR WINDSCREEN	New	150.00	120.00
4	TO REMOVE & REFIT TAILGATE MECHANISM	New	100.00	60.00
5	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	New	600.00	400.00
6	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	100.00	30.00
7	TO VACUUM ,WAXING & CLEAN	New	50.00	0.00
8	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	New	50.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>2,150.00</b>	<b>1,040.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >