

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	HSBC LIFE (SINGAPORE) PTE LTD		Ref:	CS3/HSB23004091/Tvp3m4	
	10 MARINA BOULE	EVARD #48-01 MARINA BAY RE TOWER 2 SINGAPORE	Date:	12/05/2023	
	ATTN: KHOR SAW	THENG	Code:	HSB	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 7773X	Veh. Inspected	FBU 7240T	
	Policy No.	VFX/P2419140	Coverage (\$)	0.00	
	Claim No.	S3M04LF3	Excess (\$)	0.00	
	Assign From	KHOR SAW THENG	Assign Date	20/04/2023	
2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA AEROX	c.c	155	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	MH3SG4640KJ058181	Colour	GREY	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	110/80 R14	MICHELIN	5 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	140/70 R14	MICHELIN	5 mm	
	L/H Rear Tyre			mm	
4.	4. Description of Damages				
	THE VEHICLE SUS BODY.	STAINED DAMAGES AT THE FRO			
5.	General Information				
	Accident Date	08/04/2023	Inspect Date / Time	20/04/2023 (01:24 PM)	
	Survey held at	B3014, UBI RD 1 #01-322 S4087	702		
	Repairer	KANEX MOTORSPORTS PTE LTD			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500-\$5,500				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:	6 Work	ing Days	
	Report Ref No. CS3/HSB23004091/Tvp3m4				

Report Ref No. CS3/HSB23004091/Tvp3m4

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser