

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23004096/UQP3Q2**Date:** 10/05/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00268112201		
<b>Claimant Vehicle No :</b>	SMW2317Z	<b>Insured Vehicle No :</b>	SMQ7314E		
Date of Loss:	19/04/2023	Nature of Claim:	TP	Claim No:	SNM23D202872/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMW2317Z</b>		Engine No:	2ZR2F98611
Make & Model:	TOYOTA PRIUS, 1.8 PLUS (A)		Chassis No:	JTDZS3EU00J053354
Reg. Date:	10/11/2020 (Man. Year: 2019)		Odometer:	21236 km
Colour:	Brown			
Engine Capacity:	1798 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,331.90	1,503.05	3,828.85	71.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	770.00	490.00	38.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,591.90</b>	<b>2,273.05</b>	<b>4,318.85</b>	<b>65.52</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>6,591.90</b>	<b>1,800.00</b>	<b>4,791.90</b>	<b>72.69</b>

INSPECTION

Date of Assignment:	24/04/2023		
Date Inspected:	25/04/2023	Inspected At:	Super-zee Motor Service (HQ) BLK 14 DEFU LANE 10, #01-402 Singapore 539195
Estimated Period of Repair:	2.0 days		

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 10 May 2023)
<b>Parts:</b> 144	TOYOTA PRIUS 1.8 PLUS (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SMW2317Z)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	780.80 F	*669.10 FL
2	1		*REAR BUMPER LOWER SPOILER	Grazed	1,715.80 F	*1,018.30 FL
3	2		*REAR BUMPER RETAINERS	Not Necessary	382.60 F	*- FL
4	2		*REAR BUMPER BRACKETS	Not Necessary	363.80 F	*- FL
5	1		*REAR BUMPER BEAM	Serviceable	395.50 F	*- FL
6	10		*REAR BUMPER CLIPS	Necessary	65.00 F	*50.00 FL
7	1		*REAR END PANEL	Repair	838.40 F	*- FL
8	2		*REVERSE SENSOR	Shorted	790.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,331.90</b>	<b>1,937.40</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	0.00	434.35
<b>Total Parts (\$\$)</b>	<b>5,331.90</b>	<b>1,503.05</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANELBEAT WHERE NECESSARY	New	550.00	350.00
2	TO PUTTY ,APPLY PRIMER & SPRAYPAINT AFFECTED PORTION	New	550.00	400.00
3	TO APPLY RUSTPROOFING ON REPAIRED ,REPLACED PANEL	New	100.00	0.00
4	TO CHECK ELECTRICAL WIRING FUNCTIONS	New	60.00	20.00
			<b>Gross Labour Cost (S\$)</b>	<b>770.00</b>
			<b>1,260.00</b>	<b>770.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >