

ASS. REC. BY:

REF:

SMR/23004109/KV

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: _____

at Workshop m/s Hwa Sey

of _____

Insured: SMB 1380G

Policy No. _____

Claims No. BUS/04/23/5022


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: BJT 679 Yr Regn: 12, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (m)

Make: Toyota Hiace c.c. 2494

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 243018 T/Radio: Insured / Std / NI / NA

Eng/No: 14

C/No: PN1H4S02P X04000300

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NTI / S/Rim / STD A/Rim or

Tyre Size: F: 195R15X8

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 17/4/23 D.O.I. 9/5/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>18/5/23</u>	<u>11 Pm @ 27501 Cukur (red 2354.05, 46%)</u>

Date/Time, File Pass to? : Prell. Report : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:
Transportation:
S - RS. SI
Fixt. Cos
Others
TOTAL

Add Fee: : Site Insp (\$) : Interview (\$) : Tech Invs (\$) : Weekend (\$)

Report Format : TP
Lump Sum / I.B.L: (\$ 2750)



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

SLVTKJH

No. Pendaftaran : BJT679
No. ID : 870514385163
Nama Pemunya Berdaftar : BEH CHU CHIN
Alamat : LC 48 KAMPUNG BARU TAIPING
34650 KUALA SEPETANG PERAK

No. Chasis/No. Enjin : PN1HS02PX04000300 / 2KD9656223
Buatan>Nama Model : TOYOTA / TOYOTA HIACE W/VAN 2.5 (TD)
Keupayaan Enjin : 2494
Bahan Bakar : DIESEL HIJAU
Status Asal : PEMASANGAN TEMPATAN
Kelas Kegunaan : PSDN-JIP/VAN/BAS/KVN IND
Jenis Badan/Tahun Dibuat : WINDOW VAN / 2006
Tarikh Pendaftaran : 07/12/2007
B. D. M/B. G. K/BTM : -/-/-
Syarat Pendaftaran 1 : -
Syarat Pendaftaran 2 : -
Syarat Pendaftaran 3 : -



**SINGAPORE
POLICE FORCE**



T/20230417/2020

Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999

3 of 3

Report No. T/20230417/2020

CONTINUATION OF REPORT

Signature of Officer Recording The Report: D / SGT 2 ANG BINGLUN, BRENDON	
Signature Of Interpreter: Not applicable	
Officer In Charge Of Case: TP / AEIT / SR STAFF SGT MUHAMMAD NOOR BIN ABDUL RAHMAN Contact No.: 65476219	

Signature Of Informant:	
Date/Time: 17/04/2023 10:58	
Classification Of Case:	



Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999

CONTINUATION OF REPORT

Driver			
Name	BEH CHU CHIN	ID No.	G7834717T
Related Vehicle	BJT679 (Van)	Contact No.	83393282
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 17/04/2023 at about 0814hrs, I was driving my Malaysian vehicle BJT679 along Jurong East Avenue 1 heading towards Toh Guan Road. Just before the cross junction of Jurong East Avenue 1 and Jurong East Central, the traffic light signal turned red as such I braked and stopped. Subsequently, I felt an impact on my rear. I alighted and saw one SMRT Bus bearing registration plate number SMB1380G had collided into my rear of vehicle. At the point of time, no one was injured. We exchange contact number, and left the scene. A few moments later, I received a call from the driver of the SMRT Bus and told me to proceed back to the scene as they require police assistance which I did.

The police then arrived, and I was asked to lodge a police report. My vehicle sustained dents on the rear door and is unable to lock due to the damages. The rear tail light was also damaged. I do not have any in-car camera on my vehicle.

HWA SENG SPRAY PAINTING PTE LTD

160 Sin Ming Drive
 #05-11 Sin Ming Autocity
 SINGAPORE 575722
 (COMPANY REGISTRATION NO.: 202017045G)
 TEL : 64533100
 FAX : 62669932

Date of Accident: 17/04/2023

Your Insured

Vehicle No.: SMB 1380G

NOT Withheld
 LRP @ 2750k
 Resurvey After Paint
 4 days

ESTIMATE REPAIR COSTS TO TOYOTA HIACE REG. NO. : BJT 679

S\$

1pc	Tailgate	2110.60	By	2421.30	✓
1pc	Logo		na	72.20	✓
1pc	Upper Lock		R	299.60	X
1pc	Lower Lock		R	106.80	X
1pc	Rubber		Sm	486.00	X
1pc	Taillamp LH		CM	331.10	✓
1pc	Corner Panel		R	111.20	X
1pc	Rear Bumper		Bu	491.60	✓
1pc	End Panel		R	371.40	X
1pc	Rear Boot C/Garnish		warp	154.20	✓
					4845.40
			Less : 25%		1211.35
					3634.05

LABOUR & MISC CHARGES

Panel Knocking	500.00	4501
Spray Painting	550.00	4001
Wire Checking	80.00	201
Labour to Remove & Install Rear Windscreen	200.00	1201
Sealant & Clip	nec 80.00	6001
Inner Seal	nec 60.00	3001

5104.05

HWA SENG SPRAY PAINTING PTE LTD



LKK AUTOCENTERS hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: