

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS23004112/KVY3E2**Date:** 09/05/2023REFERENCE

Handling Insurer: ECICS Limited

Policy No:

**Claimant Vehicle No :**

SKQ7488K

**Insured Vehicle No :**

SME7631C

Date of Loss: 19/04/2023

Nature of Claim:

TP

Claim No:

DMPC2300277H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

**SKQ7488K**

Make &amp; Model:

TOYOTA ALPHARD, 2.4 CVT (A)

Engine No:

2AZG455348

Reg. Date:

23/12/2014 (Man. Year: 2014)

Chassis No:

ANH208348873

Colour:

Metallic Grey

Odometer:

151913 km

Engine Capacity:

2362 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

**Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

235/50 R18

Rear Tyre Size:

235/50 R18

Front Left Side:

Bridgestone 9 mm

Rear Left Side:

Kumho 7 mm

Front Right Side:

Bridgestone 9 mm

Rear Right Side:

Kumho 7 mm

*The above values represent the remaining tyre treads depth*COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	14,173.05	4,489.07	9,683.98	68.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,660.00	1,490.00	2,170.00	59.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>17,833.05</b>	<b>5,979.07</b>	<b>11,853.98</b>	<b>66.47</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,750.00</b>		
<b>(S\$)</b>	17,833.05	4,750.00	13,083.05	73.36
<b>+ GST 8.00/8.00% (S\$)</b>	1,426.64	380.00	1,046.64	73.36
<b>Nett Amount (S\$)</b>	<b>19,259.69</b>	<b>5,130.00</b>	<b>14,129.69</b>	<b>73.36</b>

INSPECTION

Date of Assignment:

20/04/2023

Date Inspected:

25/04/2023 Inspected At:

Sin Ming Autocare BFG Pte Ltd (HQ)

176, Sin Ming Drive #02-05, Sin Ming Autocare

Complex

Singapore 575721

Estimated Period of Repair:

5.0 days

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2023)
<b>Parts:</b>	M1-MPV	TOYOTA ALPHARD 2.4 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKQ7488K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER (REAR)	Buckled	1,037.40 F	*1,037.40 FL
2	1		*BUMPER RETAINER (RLH)	Serviceable	95.00 F	*- FL
3	1		*BUMPER RETAINER (RLR)	Serviceable	95.00 F	*- FL
4	1		*BUMPER (REAR BRACKET LH)	Repair	85.60 F	*- FL
5	1		*BUMPER (REAR BRACKET RH)	Repair	85.60 F	*- FL
6	1		*BUMPER REFLECTOR LH	Serviceable	108.35 F	*- FL
7	1		*BUMPER REFLECTOR RH	Serviceable	108.35 F	*- FL
8	10		*BUMPER (REAR CLIPS)	Necessary	50.00 F	*50.00 FL
9	1		*TAIL GATE (REAR)	Bent	2,522.00 F	*2,120.30 FL
10	1		*TAIL GATE CENTRE LOGO(REAR)	Necessary	178.15 F	*178.15 FL
11	1		*TAILGATE OUTER CHROME HANDLE (REAR)	Serviceable	485.15 F	*- FL
12	1		*TAIL LOCK GATE LOCK (REAR)	Repair	561.30 F	*- FL
13	1		*TAILGATE OUTER GARNISH (REAR)	Serviceable	1,990.00 F	*- FL
14	1		*TAILGATE EMBLEM ALPHARD (REAR)	Necessary	115.35 F	*115.35 FL
15	1		*TAILGATE DAMPER (REAR RH)	Serviceable	392.30 F	*- FL
16	1		*TAILGATE DAMPER (REAR LH)	Serviceable	392.30 F	*- FL
17	1		*TAILGATE INNER TRIM BOARD (REAR)	Mtg Cracked	985.15 F	*710.60 FL
18	1		*TAIL LAMP LH	Serviceable	500.00 F	*- FL
19	1		*TAIL LAMP RH	Serviceable	500.00 F	*- FL
20	1		*END PANEL TOP GARNISH (REAR)	Mtg Distorted	235.15 F	*235.15 FL
21	1		*END PANEL (REAR)	Bent	915.00 F	*915.00 FL
22	1		*CORNER GARNISH (REAR)RH	Serviceable	365.15 F	*- FL
23	1		*BEZA SENSOR (REAR)	Dented	265.15 F	*265.15 FL
24	1		*ANTENNA SENSOR (REAR)	Serviceable	285.15 F	*- FL
25	1		*CORNER GARNISH (REAR)LH	Serviceable	365.15 F	*- FL
26	1		*TAIL GATE RUBBER (REAR)	Serviceable	395.00 F	*- FL
27	1		*BUMPER REVERSOR (REAR) RH	Shorted	425.15 F	*265.00 FL
28	1		*BUMPER REVERSOR (REAR)LH	Serviceable	425.15 F	*- FL
29	1		*NUMBER PLATE (REAR)	Serviceable	50.00 FS	*- FS
30	1		*GLASS SEALANT (REAR)	Necessary	50.00 FS	*40.00 FS
31	1		*NUMBER PLATE HOLDER (REAR)	Serviceable	30.00 FS	*- FS
32	1		*SEALANT END PANEL AND REAR BOARD	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>14,173.05</b>	<b>5,962.10</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	<b>0.00</b>	<b>1,473.03</b>
<b>Total Parts (\$\$)</b>	<b>14,173.05</b>	<b>4,489.07</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANEL BEAT WHERE NECESSARY	New	1,800.00	600.00
2	TO APPLY RUST-PROOFING ON REPAIRD/REPLACE PANEL	New	200.00	30.00
3	TO REMOVE /TRANSFER TAILGATE MECHANISM	New	180.00	60.00
4	TO REMOVE/REFIT REAR TAIL GATE GLASS	New	180.00	120.00
5	TO CHECK WIRING FUNCTIONS	New	100.00	20.00
6	TO PUTTY ,APPLY PRIMER & SPRAY-PAINT ON THE EFFECTED PORTION	New	1,200.00	660.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,660.00</b>	<b>1,490.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >