



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3372X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LH/SIDE WING MIRROR	CRACKED	670.00	670.00
1	ROCKER GARNISH LH	NOT NECESSARY	732.80	-
	LESS 20% DISCOUNT		-280.56	-134.00
			1,122.24	536.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR DOOR COMFORT APP STICKER (SN)	NOT NECESSARY	80.00	-
			80.00	-
	<u>LABOUR</u>			
	PANEL BEATING.		450.00	140.00
	SPRAY PAINTING CHARGE.		700.00	100.00
			1,150.00	240.00
	GRAND TOTAL		2,352.24	776.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			600.00

Report Ref No. NS/INC23004120/Tnp3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.