-	-	**		
1-0		F	٠	
1.7	_	1		

/ N C NS/INC23004120/Tnp3

ASSI0	GNIVLENT				
From: Date:	Veh No: 41C 3372X Yr Regn: 2016, April.				
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxt / Prime Mover /				
OD (TP) WS I TP RES I OD RES I EVA I INV I MV	Truck / Trailer or				
To Inspect Vehicle No:	Make: Myrnder 140 c.c 1685				
at Workshop m/s	Colour A/C: Insured / Std / NI / NA				
of	Sp.Reading (258/10) T/Radio; Insured / Std / NI / NA				
Insured:	Eng/No:				
Policy No.	C/No: 14M 4 LB 41 4 M & 408-7798				
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt				
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or				
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or				
Make of Veh:	Modi: 1 S/Rim / STD A/Rim or				
	Tyre Size: F: 205/60R16				
(Policy Condition)	R: ~ ~ ~				
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /				
repair at the time of inspection.	TOYO/YOKO or Westlake.				
Bal. or Market Value:	<u>Front</u> <u>Rear</u>				
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. R/Bal. 6 mm				
GIA / PR Seen: Consistent? : Yes or No	L/Bal 6. mm L/Bal 6 mm				
Est. Repairs: 1 days Res.: Yes or No	D.O.A. D.O.I. 20/4/23				
Lum Sum: % 3 Val.: Yes or No	Survey held at Courfut Louyery.				
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or				
Date: Person Contacted: Vehicle: IN / OUT	The U/C / Chassis frame / Body Structure affected due to collision.				
Date / Time Action / Instruction	The O/C / Chassis frame / Body structure amound due to semi-lem				
Date / Time Action / Times action					
Taufikh confirmed lump sum \$600 and	1 day				
(red, \$1752.24, 74%)	1				
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 1				
1) : Final Report	Resurvey No. of Trip: 1 Survey Fee:				
Date/Time, File Return to?	Transportation:				
2) Add F	ee:: Site Insp (\$)s+Rssi				
	:Interview (\$) Photos				
Reperit Formati:	: Tech. Invs (\$) Others				
Lump Sum / LBJ: (F)	:Westend (\$)				
	TOTAL				

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO

SHC3371X

SHL 3372X

19.04.2023

MAKE

REG 21.04.2016

MODEL

1-40

CHIANG/ INCOMP

Parts Description/ Labour	Туре	Unit Price	Amount
LH/SIDE WING MIRROR		Col	\$670.00
ROCKER GRANISH LH		olddamagh	× \$732.80
SUB TOTAL		٥	\$1,402.80
20.00%			\$280.56
			\$1,122.24
REAR DOOR COMFORT APP STICKER			火 \$80.00
			\$80.00
Labour Charge			
Panel Beating		/4	\$450.00
Spray Painting Charge		/6	\$700.00
TOTAL LABOUR			\$1,150.00
ESTIMATE TOTAL			\$2,352.24
ESTIMATE TOTAL			\$2,352.24
This is an initial estimate based on a visual inspection of the	above vehic	le. The final repair qua	antum will
be prepared after the vehicle is surveyed by a motor Survey	or appointed	by the insurance con	npany.
	LH/SIDE WING MIRROR ROCKER GRANISH LH SUB TOTAL 20.00% REAR DOOR COMFORT APP STICKER Labour Charge Panel Beating Spray Painting Charge TOTAL LABOUR ESTIMATE TOTAL This is an initial estimate based on a visual inspection of the	LH/SIDE WING MIRROR ROCKER GRANISH LH SUB TOTAL 20.00% REAR DOOR COMFORT APP STICKER Labour Charge Panel Beating Spray Painting Charge TOTAL LABOUR ESTIMATE TOTAL This is an initial estimate based on a visual inspection of the above vehice	LH/SIDE WING MIRROR ROCKER GRANISH LH SUB TOTAL 20.00% REAR DOOR COMFORT APP STICKER Labour Charge Panel Beating Spray Painting Charge TOTAL LABOUR

Tauflin 97495749

WP 20/4/73 & 4pm

1/5 Resum after report

taufith ellchauto wn

Oldan

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after sprey painting
- To display damaged part(s) during resurvey Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal me facation(s) a allowed
- Suppler ieritary item(s) miust be resurveyed and is subilict to final application Insurance Company

Acknowledged by Repairer piqual re:



of Service Advisor

returned to Service Reception upon collection

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops
205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
Date/Time: 452 mdar Grad Singapore 508088:13

Page: 1

JOB CARD Sales Order: 5893706 ARC Repair TP(CLSO)1 'eam: JC NO305551728 REGN NO. SHC3372X STOMER MILEAGE COMFORT TRANSPORTATION PTE LTD MAKE HYUNDAI /MS FUEL 7010045 STOMER NO. 383 SIN MING DRIVE MODEL 19.04.2023 16:15 Singapore SINGAPORE 575717 I - 4065508755 . (R) YR OF MANU. 2016 TARGET DATE (P) CHASSIS CODE KMHLB41UMGU087798 COMPLETION DATE/TIME: COUNT CARD NO. JOB DESCRIPTION Accident Date: 19.04.2023 VATURE: 3P 19.04.2023 ' FRONT 3/NO LABOR CODE DESCRIPTION LEFT SIDE ECKED & PASSED OUT BY: SERVICE ADVISOR CUSTOMER'S SIGNATURE wledgement Slip **Exit Pass** Vehicle No.: SHC3372X CHIANG SHC3372X ∍ No.:

Name of Service Advisor

To be kept by Security Guard

Date

Signature/Date