

Ding Auto Pte Ltd (Co.Reg.No:201311788Z)

176 Sin Ming Drive #04-06, Sin Ming Autocare

Singapore 575721

Tel: 64521208 Fax: 64520614 Email: ding@dingauto.sg;kenneth.ding@dingauto.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2004136068-01	Date of Loss:	19/04/2023
Vehicle Reg. No.:	SJS9919Y	Driveable?	
Driver Age/Info:	25 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHEE YOKE PENG	Contact No:	+6597579618
Driver:	CHIANG ZHEN ANN		

Make/Model:	TOYOTA HARRIER, 2.0 ELEGANCE CVT (A)	Vehicle Reg. Date:	26/01/2017
Vehicle Colour:	WHITE	Chassis No:	ZSU600088015
Engine No:	3ZRB871559		
Odometer:	140102 KM		

Paint Type:
Total Loss?
Est. Duration of Repair
(day)

NO

14 5

Description of Accident/Loss COLLISION - HEAD TO REAR
Present Location: DING AUTO PTE LTD (HQ)

COST OF CLAIMS	Amount
Parts	9,388.50
Miscellaneous Items	250.00
Labour	3,360.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	12,998.50
+ GST 8.00% (\$\$)	1,039.88
Nett Amount (\$\$)	14,038.38

This claim is handled by: LYNN YAP WEI LIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

26/1/2017

9196

254 60 608 8015

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronized: 20 Apr 2023)

Parts: M1-SUV TOYOTA HARRIER 2.0 ELECTRIC CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ding Auto Pte Ltd/SJS9919Y/20/04/2023 16:01

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	*315.00 F BR
2	1		*LOWER GRILLE	0.00	0.00	*145.00 F DIS
3	1		*LOWER LIP	0.00	0.00	*150.00 F ?
4	1		*FRONT BUMPER RETAINER LHS	0.00	0.00	*55.00 F ?
5	1		*FRONT BUMPER RETAINER RHS	0.00	0.00	*55.00 F ?
6	1		*FRONT GRILLE	0.00	0.00	*265.00 F CRA
7	1		*FRONT FENDER LHS	0.00	0.00	*375.00 F XR
8	1		*FRONT FENDER RHS	0.00	0.00	*375.00 F XR
9	1		*FRONT FENDER INNERSHIELD COVER LHS	0.00	0.00	*220.00 F ?
10	1		*FRONT FENDER INNERSHIELD COVER RHS	0.00	0.00	*220.00 F ?
11	1		*FRONT HEADLAMP LHS	0.00	0.00	*1,180.00 F ?
12	1		*FRONT HEADLAMP RHS	0.00	0.00	*1,180.00 F BR
13	1		*HEADLAMP BRACKET LHS	0.00	0.00	*55.00 F X NN
14	1		*HEADLAMP BRACKET RHS	0.00	0.00	*55.00 F ?
15	1		*FOG LAMP ASSY LHS	0.00	0.00	*135.00 F X NN
16	1		*FOG LAMP ASSY RHS	0.00	0.00	*135.00 F ?
17	1		*FOG LAMP GARNISH LHS	0.00	0.00	*80.00 F X NN
18	1		*FOG LAMP GARNISH RHS	0.00	0.00	*80.00 F ?
19	1		*BONNET	0.00	0.00	*560.00 F XR
20	1		*BONNET HINGE LHS	0.00	0.00	*38.00 F X NN
21	1		*BONNET HINGE RHS	0.00	0.00	*38.00 F X NN
22	1		*BONNET ABSORBER	0.00	0.00	*150.00 F X NN
23	1		*BONNET WEATHER STRIP	0.00	0.00	*48.00 F X NN
24	1		*BONNET LOCK	0.00	0.00	*95.00 F ?
25	1		*RADIATOR TOP GARNISH	0.00	0.00	*195.00 F ?
26	1		*FRONT REINFORCEMENT	0.00	0.00	*180.00 F ?
27	1		*FRONT SUPPORT PANEL	0.00	0.00	*400.00 F ?
28	1		*RADIATOR	0.00	0.00	*625.00 F ?
29	1		*CONDENSER	0.00	0.00	*625.00 F ?
30	1		*TOWING CAP LHS	0.00	0.00	*18.00 F X NN
31	1		*TOWING CAP RHS	0.00	0.00	*18.00 F X NN
32	1		*FRONT BUMPER LOWER COVER	0.00	0.00	*110.00 F X NN
33	1		*FRONT BRACE PANEL	0.00	0.00	*120.00 F ?
34	1		*HIGH HORN	0.00	0.00	*65.00 F X NN
35	1		*LOW HORN	0.00	0.00	*65.00 F X NN
36	1		*FRONT REINFORCEMENT CENTRE SPONGE	0.00	0.00	*80.00 F ?
37	1		*FRONT REINFORCEMENT SIDE SPONGE	0.00	0.00	*30.00 F ?

F=Franchise part.

Sub Total (\$\$)

8,535.00

+ Margin on L,N Items 10.00% (\$\$)

853.50

Ding Auto Pte Ltd/SJS9919Y/20/04/2023 16:01. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT BUMPER, FRONT INNERSHIELD LHS, FRONT INNERSHIELD RHS & BONNET CLIPS	200.00
2	1	FRONT CARPLATE WITH FRAME	50.00
Sub Total (S\$)			250.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	REPAIR, PANEL BEAT & STRAIGHTEN - ACCIDENT AREAS	New	1,600.00
2	SPRAY PAINT - FRONT BUMPER, FRONT FENDER LHS, FRONT FENDER RHS, FRONT BONNET	New	1,200.00
3	ALIGN HEADLAMP & TEST WIRING	New	120.00
4	REMOVE & INSTALL - CONDENSER & RADIATOR	New	200.00
5	REMOVE & REFIT - BONNET COMPONENTS	New	120.00
6	REFILL AIRCON GAS & COOLANT	New	120.00
Gross Labour Cost (S\$)			3,360.00

Ding Auto Pte Ltd/SJS9919Y/20/04/2023 16:01. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- NOT AUTHORISE
- EXCESS \$ 600
- P/P OR L/S REPAIR?
- SURVEY BY EDWARD TEL 62563561
- RESURVEY BEFORE PAINT FOR P/P REPAIR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4/21/23, 3:59 PM

Repairer Estimates

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
Total Parts (S\$)						9,388.50

Ding Auto Pte Ltd/SJS9919Y/20/04/2023 16:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS