

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23004133/UVP3E2**Date:** 09/05/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00003682301
Claimant Vehicle No :	PD200D	Insured Vehicle No :	SKR6873H
Date of Loss:	18/04/2023	Nature of Claim:	TP
		Claim No:	SNM23D202869/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PD200D	Engine No:	1GD8382576
Make & Model:	TOYOTA HIACE, 2.8 D COMMUTER GL (A)	Chassis No:	GDH2232001395
Reg. Date:	30/04/2019 (Man. Year: 2019)	Odometer:	135008 km
Colour:	White		
Engine Capacity:	2754 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,708.90	4,187.55	1,521.35	26.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,340.00	940.00	400.00	29.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,048.90	5,127.55	1,921.35	27.26
Approved Total (Overridden) (S\$)		4,100.00		
	(S\$)	7,048.90	4,100.00	2,948.90
	+ GST 8.00/8.00% (S\$)	563.91	328.00	235.91
	Nett Amount (S\$)	7,612.81	4,428.00	3,184.81

INSPECTION

Date of Assignment:	20/04/2023		
Date Inspected:	26/04/2023	Inspected At:	Stytech Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #02-30, Kaki Bukit Autohub Singapore 417921
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2023)
Parts: 213	TOYOTA HIACE 2.8 D COMMUTER GL (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PD200D)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*RIGHT FRONT DOOR	Badly Dented	1,811.20 F	*1,721.10 FL	
2	1		*RIGHT STEP GARNISH	Grazed	167.20 F	*167.20 FL	
3	1		*RIGHT HEADLAMP	Scratched / Cracked	2,584.50 F	*2,539.10 FL	
4	1		*FRONT BUMPER	Distorted	820.60 F	*820.60 FL	
5	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS	
6	1		*FRONT BUMPER BRACKET (RIGHT)	Cracked	191.70 F	*191.70 FL	
7	1		*FRONT RIGHT INNER WIRE CASING	Cracked	103.70 F	*103.70 FL	
					Sub Total (\$\$)	5,708.90	5,573.40
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,385.85
					Total Parts (\$\$)	5,708.90	4,187.55

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSFER DOOR	New	120.00	60.00
2	CHECK WIRING	New	60.00	20.00
3	ANTI RUST PROOF	New	60.00	30.00
4	PANEL BEATING	New	400.00	350.00
5	PAINT WORK	New	700.00	480.00
			Gross Labour Cost (\$\$)	1,340.00
				940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >