## Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd. 8 Temasek Boulevard #04-01 Suntec Tower Three Singapore 038988

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Date: 25 Apr 2023

# **Preliminary Advice**

Vehicle No : YQ1451P Accident Date : 09/04/2023 Policy No. Make : HINO XZU700R : DMCG22012447

Assignment Date : 21/04/2023 Excess : S\$0.00 Date of Inspection : 24/04/2023 Est. Duration of Repair : 21

: UNIMOTOR COMPANY - KAKI BUKIT (HQ) Inspection At

1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT)

SINGAPORE 417883

## Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	41,866.00
Revised Amount	:S\$	18,528.00
Check Items (Estimated)	:S\$	18,732.00
Total	:S\$	37,260.00

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value :S\$ Pre-Accident Value :S\$ 85,000.00 COE / PARF Rebate :S\$ 17,876.00 Salvage Value :S\$

Margin for Repair :S\$ 67,124.00

### Remarks

( X )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kir	ndly
	let us have your authorisation.	

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments: Please advise the rear box and power gate with insurer policy. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.