

ASS. REC. BY:

REF: 155B/23004151/Kg

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format:

Lump Sum / I.B.I: (\$

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) \$ - RS. \$

) Fines

) Others

TOTAL

Veh No:

SMK 9255K

Yr Regn:

04, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Jazz

c.c

1498

Colour

n. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

9098

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMGK 5850K 204550

Gen. Cohd: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/50R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

20/4/23

D.O.I.

28/4/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

EDWIN GARAGE AIRCON & REPAIR

BLK 5032 Ang Mo Kio. Industrial Park 2 . #01-295. Singapore 569535

Tel: 97856612

Vehicle No: SMK9255K
Model : HONDA/JAZZ RS

PARTS	QTY	AMOUNT	
REAR BUMPER	1	\$ 516.60	✓
REAR BUMPER SIDE RETAINER LH/RH	2	\$ 36.34	✓
REAR BUMPER GARNISH	1	\$ 41.16	✓
REAR BUMPER SIDE COVER LH/RH	2	\$ 44.52	X
REAR END PANEL	1	\$ 330.33	✓
REAR END PANEL INNER GARNISH	1	\$ 63.84	✓
REAR FLOOR PANEL TOP BOARD	1	\$ 204.44	X
REAR FLOOR PANEL SPONGE COMPARTMENT BOX	1	\$ 126.53	✓
REAR TAILLAMP LH/RH	2	\$ 536.76	✓
TAILGATE	1	\$ 818.16	✓
TAILGATE INNER TRIMBOARD	1	\$ 64.37	✓
TAILGATE LOCK	1	\$ 94.61	✓
TAILGATE OUTER GARNISH ASSY	1	\$ 118.02	X
REAR 'LOGO' EMBLEM	1	\$ 22.35	✓
REAR 'JAZZ' EMBLEM	1	\$ 28.54	✓
REAR 'RS' EMBLEM	1	\$ 26.85	✓
REAR TAILGATE WEATHERSTRIP	1	\$ 96.92	✓
REAR WINDSCREEN MOULDING	1	\$ 47.90	✓
		\$ 3,218.24	
		\$ 643.65	
		\$ 2,574.59	
		\$ 2,574.59	

S/NETT ITEMS

REAR NUMBER PLATE	1	\$ 50.00	45SN
REAR BUMPER CLIP	1 SET	\$ 60.00	✓
REAR END PANEL INNER GARNISH CLIP	1 SET	\$ 50.00	✓
TAILGATE INNER TRIMBOARD CLIP	1 SET	\$ 60.00	✓
REAR REVERSE SENSOR	1 SET	\$ 320.00	200SN
REAR WINDSCREEN SEALANT	2	\$ 120.00	40SN
JOINT SEALANT	2	\$ 120.00	30SN
		\$ 780.00	
		\$ 3,354.59	

LABOUR

CHECK REAR WIRING AND LIGHTING SYSTEM	\$ 100.00	20L
REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	\$ 200.00	60L
REMOVE AND REFIT TAILGATE COMPONENTS	\$ 100.00	60L
REMOVE AND REPLACE REAR WINDSCREEN	\$ 200.00	120L
REMOVE AND RENEW REAR REVERSE SENSOR	\$ 100.00	50L
REMOVE AND REFIT REAR REVERSE CAMERA	\$ 100.00	40L
PANEL BEATING ON AFFECTED AREAS	\$ 1,000.00	600L
SPRAY PAINTING ON AFFECTED AREAS	\$ 1,000.00	660L
APPLY ANTI RUST ON AFFECTED AREAS	\$ 150.00	60L
	\$ 2,950.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: