

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA23004172/UNP3Q2**Date:** 27/07/2023REFERENCE

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP311075
Claimant Vehicle No :	SMG152D	Insured Vehicle No :	SJK8233R
Date of Loss:	20/04/2023	Nature of Claim:	TP
		Claim No:	MPC04103

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG152D		
Make & Model:	TOYOTA COROLLA CROSS, 1.8 G HYBRID CVT (A)	Engine No:	2ZR2N98859
Reg. Date:	14/04/2022 (Man. Year: 2021)	Chassis No:	ZVG111007321
Colour:	Red	Odometer:	13436 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,161.20	2,032.62	4,128.58	67.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	930.00	820.00	46.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,911.20	2,962.62	4,948.58	62.55
+ GST 8.00/8.00% (S\$)	632.90	237.01	395.89	62.55
Nett Amount (S\$)	8,544.10	3,199.63	5,344.47	62.55

INSPECTION

Date of Assignment:	21/04/2023		
Date Inspected:	25/04/2023	Inspected At:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jul 2023)
Parts:	143	TOYOTA COROLLA CROSS 1.8 G HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG152D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER-RH	Dented	777.00 FL	*777.00 FL
2	1		*FRONT FENDER COWLING-RH	Serviceable	201.90 FL	*- FL
3	10		*FRONT FENDER COWLING CLIPS-RH	Not Necessary	55.00 FL	*- FL
4	1		*FRONT FENDER OUTER ARCH GARNISH-RH	Deformed	287.60 FL	*287.60 FL
5	1		*FRONT RIM TOYOTA HUB CAP-RH	Broken	358.40 FL	*358.40 FL
6	1		*FRONT DOOR LOWER GARNISH-RH	Grazed	380.50 FL	*380.50 FL
7	1		*FRONT KNUCKLE ARM-RH	Not Necessary	505.60 FL	*- FL
8	1		*FRONT KNUCKLE ARM BEARING-RH	Not Necessary	734.60 FL	*- FL
9	1		*FRONT LOWER ARM-RH	Not Necessary	914.10 FL	*- FL
10	1		*FRONT LOWER ARM BALL JOINT-RH	Not Necessary	217.60 FL	*- FL
11	1		*FRONT ABSORBER-RH	Not Necessary	567.80 FL	*- FL
12	1		*FRONT ABSORBER TOP MOUNTING-RH	Not Necessary	283.90 FL	*- FL
13	1		*FRONT STEEL RIM RH	Dented	1,918.20 FS	*680.00 FS
14	1		*FRONT TYRE-RH	Serviceable	280.00 FS	*- FS
					Sub Total (S\$)	7,482.20 2,483.50
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,321.00 450.88
					Total Parts (S\$)	6,161.20 2,032.62

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS ON FRONT DOOR RH,REMOVE,REPLACE ACCIDENT PARTS	New	650.00	300.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS (CANDY RED)	New	600.00	500.00
3	TO CHECK WIRING	New	30.00	20.00
4	TO 4 WHEEL ALIGNMENT	New	80.00	80.00
5	TO REMOVE,REFIX RIM & TYRE BALANCING	New	45.00	0.00
6	TO REMOVE,REPLACE FRONT UNDERCARRIAGE-RH	New	300.00	0.00
7	TO TUFF-KOTE	New	45.00	30.00
Gross Labour Cost (S\$)			1,750.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >