

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS/AIS23004199/SNP3E2**Date:** 27/06/2023**REFERENCE**

Insured/Claimant:	WANNECK HANS PETER	Policy No:	SP2004547943-01	
Date of Loss:	15/04/2023	Nature of Claim:	OD	Claim No: 202332007377

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ4911P		
Make & Model:	KIA SORENTO HYBRID, 1.6 SX TECH PACK SR (A)	Engine No:	G4FTNH040713
Reg. Date:	06/02/2023 (Man. Year: 2022)	Chassis No:	KNARH81GMP5139881
Colour:	Blue	Odometer:	2268 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$212,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/65 R17	Rear Tyre Size:	235/65 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,665.00	4,740.00	925.00	16.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,900.00	5,605.00	2,295.00	29.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,565.00	10,345.00	3,220.00	23.74
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	12,965.00	9,745.00	3,220.00	24.84
+ GST 8.00/8.00% (S\$)	1,037.20	779.60	257.60	24.84
Nett Amount (S\$)	14,002.20	10,524.60	3,477.60	24.84

INSPECTION

Date of Assignment:	24/04/2023	
Date Inspected:	24/04/2023	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days	

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2023)
Parts:	M1-SUV	KIA SORENTO HYBRID 1.6 SX TECH PACK SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ4911P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*W/STRIP-DR BODY SIDE RH (NPA)	Not Necessary	0.00 FS	*- FS
2	1		*W/STRIP-FR DR BELT I/S RH (NPA)	Not Necessary	0.00 FS	*- FS
3	1		*PAD-FR DR O/S HDL HINGE, RH (NPA)	Not Necessary	0.00 FS	*- FS
4	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
5	1		*PANEL ASSY-FENDER, RH	Dented	702.00 FS	*702.00 FS
6	1		*INSULATOR-FENDER UPPER, RH	Not Necessary	17.00 FS	*- FS
7	1		*INSULATOR-FENDER RH	Not Necessary	31.00 FS	*- FS
8	1		*GARNISH-FENDER SIDE UPR, RH	Scratched	88.00 FS	*88.00 FS
9	1		*GARNISH-FR DR RH	Missing	117.00 FS	*117.00 FS
10	1		*GARNISH ASSY-FNDR SIDE, RH	Necessary	76.00 FS	*76.00 FS
11	1		*GARNISH ASSY-FR DR SIDE, RH	Missing	177.00 FS	*177.00 FS
12	1		*GARNISH ASSY-RR DR SIDE, RH	Not Necessary	210.00 FS	*- FS
13	1		*MOULDING ASSY-SIDE SILL, RH	Not Necessary	129.00 FS	*- FS
14	1		*MIRROR ASSY-OUTSIDE RR VIEW, RH	Scratched	1,559.00 FS	*1,559.00 FS
15	1		*PANEL ASSY-FRONT DOOR, RH	Buckled	1,411.00 FS	*1,411.00 FS
16	2		*HINGE ASSY-FRONT DOOR, RH	Not Necessary	64.00 FS	*- FS
17	1		*MOULDING ASSY-FR DR FRAME, RH	Necessary	46.00 FS	*46.00 FS
18	1		*GARNISH ASSY-DR FRAME RH	Necessary	48.00 FS	*48.00 FS
19	1		*W/STRIP ASSY-FR DR BELT O/S RH	Not Necessary	90.00 FS	*- FS
20	1		*W/STRIP ASSY-FR DR SIDE RH	Not Necessary	75.00 FS	*- FS
21	1		*HANDLE ASSY-DOOR OUTSIDE, RH	Not Necessary	136.00 FS	*- FS
22	1		*COVER-FR DR O/S HDL RH	Not Necessary	15.00 FS	*- FS
23	1		*PAD-FR DR O/S HDL COVER, RH	Not Necessary	5.00 FS	*- FS
24	1		*BASE ASSY-FR DR O/S HANDLE RH	Not Necessary	76.00 FS	*- FS
25	1		*CHECKER ASSY-FRONT DOOR, RH	Missing	50.00 FS	*50.00 FS
26	1		*COVER-FR CHECKER	Not Necessary	7.00 FS	*- FS
27	1		*WIRING ASSY-FR DR (DRIVER)	Broken	436.00 FS	*436.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	5,665.00	4,740.00
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW RHF FENDER & RHF DOOR. REPAIR RHF DOOR PILLAR & RHR DOOR	New	3,840.00	2,560.00
2	RESPRAY RHF FENDER, RHF DOOR, RHF DOOR PILLAR, RHR DOOR & RH WINGMIRROR	New	2,750.00	1,925.00
3	REMOVE & REFIT RHF DOOR COMPONENT	New	280.00	280.00
4	REMOVE & REFIT RHF TRIM & CARPET TO FACILITATE REPAIR	New	280.00	280.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	100.00	100.00
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	280.00	280.00
7	APPLY ANTI CORROSION ON AFFECTED AREAS	New	250.00	100.00
8	SUPPLY BODY PNL SEALANT	New	120.00	80.00
Gross Labour Cost (\$\$)			7,900.00	5,605.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >